#### Note: This document has not been finalised.

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte.

Ltd.

4 Shenton Way

#21-01 SGX Centre 2 Singapore 068807

From: LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park

Singapore 408933

Attn: Christina Wong Date: 18 Mar 2022

# **Preliminary Advice**

Insured : SFV3434A

Vehicle No

TP Vehicle Accident Date : SMQ9386J : 02/11/2021

No

Make : HONDA CIVIC Assignment Date: 08/11/2021

Date of : 09/11/2021 Est. Duration of : 2

Inspection Repair

Inspection At: ADVANCE AUTO GARAGE (HQ)

23 KAKI BUKIT AVENUE 4 #04-01 AAS KAKI BUKIT CENTRE

SINGAPORE 415933

### **Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross) :S\$ 4,304.40 **Revised Amount** :S\$ 1,574.24 Check Items (Estimated) :S\$ 0.00 Total :S\$ 1,574.24

Lump Sum Repair :S\$ 1,250.00

#### **Total Loss Consideration**

New for Old Value :S\$ Pre-Accident Value :S\$ COE / PARF Rebate :S\$ Salvage Value :S\$ Margin for Repair :S\$

| Remarks | Re | ma | rks |
|---------|----|----|-----|
|---------|----|----|-----|

| (    | ) | The vehicle is economical for repair     |
|------|---|--|
| (    | ) | The vehicle is not economical for repair |
| (    | ) | Part-by-Part repair                      |
| ( X  | ) | Lump Sum repair                          |
| , ,, |   | <del>-</del>                             |

( X ) The above survey was conducted on a 'without prejudice' basis.

Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour cost.