

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG21011353/UES3Q2**Date:** 11/01/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070155538-01
Claimant Vehicle No :	SKV1000Y	Insured Vehicle No :	YQ1807Y
Date of Loss:	03/11/2021	Nature of Claim:	TP
		Claim No:	2352473745SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKV1000Y	Engine No:	G4FMMU238358
Make & Model:	HYUNDAI AVANTE, 1.6 (A)	Chassis No:	KMHLN41ETMU136873
Reg. Date:	06/02/2021 (Man. Year: 2021)	Odometer:	16341 km
Colour:	White		
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/40 R18	Rear Tyre Size:	225/40 R18
Front Left Side:	Kumho 8 mm	Rear Left Side:	Kumho 8 mm
Front Right Side:	Kumho 8 mm	Rear Right Side:	Kumho 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,279.20	0.00	2,279.20	100.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,690.00	950.00	1,740.00	64.68
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	4,969.20	950.00	4,019.20	80.88
+ GST 7.00/7.00% (S\$)	347.84	66.50	281.34	80.88
Nett Amount (S\$)	5,317.04	1,016.50	4,300.54	80.88
+ Car Rental (2.0 x S\$100.00/day) (S\$)		200.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		1,218.50		

INSPECTION

Date of Assignment:	08/11/2021	
Date Inspected:	08/11/2021	Inspected At: Fastech Auto Pte Ltd (HQ) 1 Kaki Bukit Ave 6, #01-46/48/50 Autobay Singapore 417883
Estimated Period of Repair:	3.0 days	

Adjuster: MARCUS CHUA**Manager:** Asher Sng Rong Yi*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR FENDER LH	Repair	1,892.00 FL	*- FL
2	1		*REAR FENDER QUARTER GARNISH LH	Not Necessary	207.00 FL	*- FL
3	1		*REAR BUMPER SIDE RETAINER LH	Not Necessary	40.30 FL	*- FL
4	1		*REAR FENDER LOWER STONE GUARD STICKER	Not Necessary	47.20 FL	*- FL
5	1		*SET REAR WINDSCREEN GLASS SEALANT	Not Necessary	80.00 FS	*- FS
6	1		*SET REVERSING SENSOR	Not Necessary	450.00 FS	*- FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (\$)					2,716.50	0.00
- List Item Discount on L Items 20.00/20.00% (\$)					437.30	0.00
Total Parts (\$)					2,279.20	0.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	APPLY ANTI RUST CHEMICAL	New	60.00	0.00
2	REMOVE AND REFIX REAR WINDSCREEN GLASS	New	150.00	0.00
3	REMOVE AND REFIX CUSHION SEAT & UPHOLSTERY ETC & REAR FENDER TRIM	New	250.00	60.00
4	REMOVE AND REFIX PETROL TANK	New	80.00	0.00
5	APPLY BODY PAINTING COATING	New	800.00	250.00
6	REMOVE & REFIX AND RENEW THE ABOVE MENTIONED PART CUT & WELDING ETC	New	650.00	400.00
7	RESPRAY PAINTING	New	550.00	200.00
8	REMOVE & REFIX & RENEW REVERSING SENSOR	New	150.00	40.00
Gross Labour Cost (\$\$)			2,690.00	950.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >