



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJT 5719D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT BUMPER	CUT / TORN	715.40	478.50
2	FRONT BUMPER SIDE RETAINER @\$65.90	O/S BENT	131.80	29.00
1	FRONT BUMPER LOWER CENTRE GRILLE	NOT NECESSARY	212.00	-
1	HEADLAMP RH	NOT NECESSARY	846.70	-
1	FRONT FENDER RH	TO REPAIR SEE LABOUR	696.20	-
1	FRONT FENDER EMBLEM "VVT"	NECESSARY	34.50	25.00
1	FRONT FENDER INNER SHIELD RH	NOT NECESSARY	142.90	-
1	FRONT FENDER MUDFLAP RH	NOT NECESSARY	156.10	-
1	FRONT KNUCKLE ARM	NOT NECESSARY	441.50	-
1	FRONT WHEEL HUB BEARING	NOT NECESSARY	185.70	-
1	FRONT LOWER ARM	NOT NECESSARY	385.40	-
	LESS 10% DISCOUNT		-394.82	-
	LESS 20% DISCOUNT		-	-106.50
			3,553.38	426.00
<u>SPECIAL NETT ITEMS</u>				
1	SET FRONT BUMPER CLIP (SN)	NECESSARY	65.00	45.00
1	SET FRONT FENDER INNER SHIELD RH CLIP (SN)	NOT NECESSARY	70.00	-
1	FRONT SPORTS RIM RH (SN)	NOT NECESSARY	850.00	-
1	FRONT TYRE RH (SN)	NOT NECESSARY	280.00	-
			1,265.00	45.00
<u>LABOUR</u>				
	CUT OFF AND REPLACE REAR RHS FENDER AND SIDE SILL PANEL RESTRUCTURE SIDE CRASH MANAGEMENT COMPONENT AND RENEW OTHER DAMAGE PARTS.INCLUSIVE OF THE REPAIR OF FRONT FENDER RH.		600.00	380.00
	SPRAY PAINTING ON DAMAGE AND AFFECTED AREA.		600.00	400.00
	ADJUST AND FOCUS FRONT LED LIGHTING SYSTEM.PERFORM HEADLAMP ADJUSTMENT TO POSITION.		80.00	20.00
	DISMENTLE AND REPLACE FRONT RHS UNDER-CARRIAGE COMPONENT.	NOT NECESSARY	200.00	-

Report Ref No. CS/SMO21011354/Uvf3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	WHEEL ALIGNMENT.	NOT NECESSARY	150.00	-
			1,630.00	800.00
GRAND TOTAL			6,448.38	1,271.00
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				1,000.00

Report Ref No. CS/SMO21011354/Uvf3n2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.