

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile						
	SOMPO INSURAN	CE SINGAPORE PL	F	Ref:	CS/SMO21011354/Uvf3n2	
	50 RAFFLES PLAC SINGAPORE LANI	CE #03-03 D TOWERSINGAPORE 048623	[Date:	08/12/2021	
			(Code:	SMO	
1.	Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	FBN 9378D	Veh. Inspected		SJT 5719D	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	CMTD2103282/AGC	Excess (\$)		0.00	
	Assign From	GRACE TEO	Assign Date		08/11/2021	
2.	2. Vehicle Particulars & Condition					
	Make & Model	HYUNDAI AVANTE (A)	c.c		1591	
	Engine No.	HIDDEN	Year of Reg.		2009	
	Chassis No.	KMHDU41BMAU892904	Colour		WHITE	
	Odometer	133076 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	GOOD				
3.	3. Conditions of Tyres					
		Size	Make		Balance	
	R/H Front Tyre	185/65 R15	DUNLOP		6 mm	
	L/H Front Tyre	185/65 R15	DUNLOP		6 mm	
	R/H Rear Tyre	185/65 R15	DUNLOP		6 mm	
	L/H Rear Tyre	185/65 R15	DUNLOP		6 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION.					
	DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	02/11/2021	Inspection Date		18/11/2021	
	Survey held at	MY CAR CONSULTANT PTE LT	D			
		60 JALAN LAM HUAT #05-21 CARROS CENTRE SINGAPORE 737869				
5a.	Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	Estimate Days of Repair					
	ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days					