

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC3/AIG21011357/APS3Q2**Date:** 14/02/2022REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800146734-03  
**Claimant Vehicle No :** SKL9086A **Insured Vehicle No :** EZ28A  
 Date of Loss: 06/11/2021 Nature of Claim: TP Claim No: 0046723535SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKL9086A**  
 Make & Model: AUDI A4, 2.0 (A) Engine No: DEM027329  
 Reg. Date: 23/12/2020 (Man. Year: 2020) Chassis No: WAUZZZF45MN004658  
 Colour: Blue Odometer: 14054 km  
 Engine Capacity: 1984 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/50 R17 Rear Tyre Size: 225/50 R17  
 Front Left Side: Hankook 6 mm Rear Left Side: Hankook 6 mm  
 Front Right Side: Hankook 6 mm Rear Right Side: Hankook 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	4,967.00	0.00	4,967.00	100.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,232.00	2,682.00	1,550.00	36.63
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>9,199.00</b>	<b>2,682.00</b>	<b>6,517.00</b>	<b>70.84</b>
<b>+ GST 7.00/7.00% (S\$)</b>	643.93	187.74	456.19	70.84
<b>Nett Amount (S\$)</b>	<b>9,842.93</b>	<b>2,869.74</b>	<b>6,973.19</b>	<b>70.84</b>
<b>+ Loss of Use (4.0 x S\$100.00/day) (S\$)</b>		400.00		
<b>+ Doc/Search Fee (S\$)</b>		2.00		
<b>Nett Liability (S\$)</b>		<b>3,271.74</b>		

INSPECTION

Date of Assignment: 16/11/2021  
 Date Inspected: 16/11/2021 Inspected At: Premium Automobiles Pte Ltd (UBI)  
 55 Ubi Road 1  
 Singapore 408699  
 Estimated Period of Repair: 4.0 days

**Adjuster:** ADRIAN LING**Manager:** CHEW HSIAO TONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Repair	2,342.00 FS	*- FS
2	1		*REAR BUMPER FIXING PARTS	Not Necessary	166.00 FS	*- FS
3	2		*REAR BUMPER SECURING STRIP-UPPER /LOWER	Not Necessary	335.00 FS	*- FS
4	1		*REAR BUMPER SPOILER	Not Necessary	249.00 FS	*- FS
5	2		*REAR BUMPER TOP GUIDE SECTION -LH/RH	Not Necessary	46.00 FS	*- FS
6	1		*REAR BUMPER GUIDE SECTION -RH	Not Necessary	45.00 FS	*- FS
7	1		*REAR WHEEL HOUSING LINER -RH	Not Necessary	240.00 FS	*- FS
8	1		*REAR WHEEL HOUSING LINER ATTACHMENT PARTS	Not Necessary	139.00 FS	*- FS
9	1		*REAR TYRE RIM -RH	Not Necessary	1,155.00 FS	*- FS
10	1		*SUNDRIES	Not Necessary	250.00 FS	*- FS

F=Franchise part. S=SpcNett.

**Total Parts (\$)**      **4,967.00**      **0.00**

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR CHECK FUNCTION	New	360.00	360.00
2	TO DISMANTLE AND RENEW REAR BUMPER TO REPAIR RHS REAR FENDER RE-ORGANIZE CRASH MANAGEMENT COMPONENTS .REINSTALL ALL PARTS REMOVED	New	1,400.00	750.00
3	TO RESPRAY REAR BUMPER AND RHS REAR FENDER	New	2,000.00	1,100.00
4	TO RENEW RHS REAR RIM AND CARRY OUT WHEEL ALIGNMENT	New	280.00	280.00
5	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
<b>Gross Labour Cost (\$)</b>			<b>4,232.00</b>	<b>2,682.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >