

HUA MENG SPRAY PAINTING WORKSHOP

1, Kaki Bukit Avenue 6, Blk C #01-61 / 01-34, Singapore 417883

Autobay @ Kaki Bukit

Tel: 6747 8064, 6746 5519 / 9666 9680 Fax: 6743 4896

ESTIMATE

JM6BM42A860324331

Name : CHNG SOO SOO AMY

Make/Model : MAZDA 3

Vehicle No : SKW8648C

Accident date : 05.11.2021

Veron

| No | DESCRIPTION | Qty | Amount (S\$) |
|-------------------|---|---------------|------------------------------|
| List Items | | | |
| 1 | Front bumper <i>Distorted</i> | 1 | \$ 1,165.70 971 |
| 2 | Front bumper side holder @ \$24.90 <i>pragd Lt.</i> | 2 | \$ 49.80 24.90 |
| 3 | Front bumper LH fod lamp <i>crackd.</i> | 1 | \$ 442.80 351 |
| 4 | Front bumper LH side garnish <i>cut</i> | 1 | \$ 85.00 ✓ |
| 5 | Front bumper reinforcement <i>Dented</i> | 1 | \$ 712.10 467. |
| 6 | Front grille <i>crackd</i> | 1 | \$ 150.80 ✓ |
| 7 | Front grille emblem <i>new</i> | 1 | \$ 55.80 ✓ |
| 8 | Front grille rim @ \$222.80 <i>LH crackd</i> | 2 | \$ 445.60 222.80. |
| 9 | Front LH headlamp <i>Cracked.</i> | 1 | \$ 974.40 ✓ |
| 10 | Front LH headlamp bulbs @ \$60.00 <i>new</i> | 2 | \$ 120.00 ✓ |
| 11 | Front LH fender <i>Distorted</i> | 1 | \$ 420.80 ✓ |
| 12 | Front LH fender inner shield <i>torn</i> | 1 | \$ 122.30 ✓ |
| 13 | Front support panel <i>Cracked.</i> | 1 | \$ 591.90 ✓ |
| 14 | Front support panel top cover <i>new</i> | 1 | \$ 116.90 ✓ |
| 15 | Front LH wheel bearing <i>Dand</i> | 1 | \$ 682.00 367. |
| 16 | Front LH knuckle arm <i>Not new</i> | 1 | \$ 483.20 ✓ |
| | | | \$ 6,619.70 |
| | | Less 20% Disc | \$ 1,323.94 |
| | | Total | \$ 5,295.76 |

4804.30
3843.44

Special Nett Items

| | | | |
|---|--|--------------|-----------------------------|
| 1 | Front bumper clips (1 set) | 1 | \$ 60.00 30 |
| 2 | Front LH fender inner shield clips (1 set) | 1 | \$ 60.00 30 |
| 3 | Front LH sport rim <i>cut</i> | 1 | \$ 1,156.80 500. |
| 4 | Front LH tyre <i>not Nec.</i> | 1 | \$ 280.00 ✓ |
| | | Total | \$ 1,556.80 |

free \$60

Labour Cost

| | | | |
|---|---|--------------|--------------------|
| 1 | To check wheel alignment | 1120 | \$ 100.00 80. |
| 2 | Remove & refix aircond fill in gas | | \$ 150.00 80. |
| 3 | Remove & refix front LH suspension | | \$ 250.00 60. |
| 4 | Remove ,replace & repair consistent to the accident | | \$ 1,200.00 500 |
| 5 | Respray painting | | \$ 1,100.00 400 |
| | | Total | \$ 2,800.00 |

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Grand Total \$ 9,652.56

Supplementary: 350
total: 5873.44
2/3: 47k.

Addressing
4/5 05/11/21
05 Days.

Not Authorized
Excess To be advised

HUA MENG SPRAY PAINTING WORKSHOP

1, Kaki Bukit Avenue 6, Blk C #01-61 / 01-34, Singapore 417883

Autobay @ Kaki Bukit

Tel: 6747 8064, 6746 5519 / 9666 9680 Fax: 6743 4896

ESTIMATE

Name : CHNG SOO SOO AMY

Make/Model : MAZDA 3

Vehicle No : SKW8648C

Accident date : 05.11.2021

| No | DESCRIPTION | Qty | Amount (S\$) |
|------------------------------|--|-------|------------------|
| <u>Supplernentary Labour</u> | | | |
| 1 | To diagnos, troublescot and to repair start stop motor | 1 | \$ 500.00 |
| | | Total | \$ <u>500.00</u> |

350

Supplementary: 350.

Aban L
H.S.