

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21011361/TPS3Q2**Date:** 02/03/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800085093
Claimant Vehicle No :	SHC7806K	Insured Vehicle No :	SMD303B
Date of Loss:	07/11/2021	Nature of Claim:	TP
		Claim No:	7366360724SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHC7806K	Engine No:	G4LEKU299953
Make & Model:	HYUNDAI AE IONIQ, 1.6 (A)	Chassis No:	KMHC851CVKU165203
Reg. Date:	06/08/2019 (Man. Year: 2019)	Odometer:	330060 km
Colour:	Yellow		
Engine Capacity:	1580 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	West Lake 6 mm	Rear Left Side:	West Lake 6 mm
Front Right Side:	West Lake 6 mm	Rear Right Side:	West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,743.92	3,086.24	657.68	17.57
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,710.00	630.00	1,080.00	63.16
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	5,453.92	3,716.24	1,737.68	31.86
+ GST 7.00/7.00% (S\$)	381.77	260.14	121.63	31.86
Nett Amount (S\$)	5,835.69	3,976.38	1,859.31	31.86
+ Loss of Use (2.5 x S\$50.00/day) (S\$)		125.00		
+ Car Rental (2.5 x S\$125.19/day) (S\$)		312.98		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		4,416.36		
Global Sum Settlement (S\$)		4,400.00		

INSPECTION

Date of Assignment:	08/11/2021	
Date Inspected:	08/11/2021	Inspected At: ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive Singapore 508969
Estimated Period of Repair:	2.0 days	

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** CHEW HSIAO TONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT BUMPER COVER	Deformed	430.90 FL	*430.90 FL
2	10		*FRT BUMPER CLIPS	Necessary	22.00 FL	*22.00 FL
3	1		*FRT BUMPER SIDE BRACKET RH	Not Necessary	28.00 FL	*- FL
4	1		*FRT BUMPER MOULDING CENTRE UPPER	Cut	368.50 FL	*368.50 FL
5	1		*HEADLAMP RH	Cracked	1,993.65 FL	*1,993.65 FL
6	1		*DAY LIGHT RH	Not Necessary	642.50 FL	*- FL
7	1		*FRT BUMPER SIDE GRILLE RH	Cut	93.45 FL	*93.45 FL
8	1		*EMBLEM BLUE -DRIVE RH	Not Necessary	26.60 FL	*- FL
9	1		*CARRIER ASSY	Cracked	949.30 FL	*949.30 FL
10	1		*FRT FENDER ADVERTISEMENT LOGO RH	Not Necessary	100.00 FS	*- FS
					Sub Total (\$\$)	4,654.903,857.80
					- List Item Discount on L Items 20.00/20.00% (\$\$)	910.98771.56
					Total Parts (\$\$)	3,743.923,086.24

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	1,050.00	350.00
2	SPRAY PAINTING CHARGE	New	600.00	250.00
3	CHECK ALL LIGHTING	New	60.00	30.00
Gross Labour Cost (\$\$)			1,710.00	630.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >