



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### TAX INVOICE

VENTURE CARS PTE LTD

33 UBI AVENUE 3  
#01-47/48 VERTEX  
SINGAPORE 408868

INV No. AC2107698

INV Date 09/11/2021

Reference CS5/TP21011364/Cq

Code TP534

#### PROFESSIONAL SERVICE FEE

Vehicle No. GR11103237

Insured Veh.

Claim No. GR11103237

Policy No.

Accident Date

Inspection Date

Description	Total
On-Site Inspection for Parallel Import Vehicle	75.00
<b>Subtotal</b>	<b>75.00</b>
<b>GST (7%)</b>	<b>5.25</b>
<b>Grand Total</b>	<b>80.25</b>

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

**FWL**



## INSPECTION CHECKLIST

Reference no: CS5/TP21011364/Cq

### Section A: Vehicle Check


Applicant	VENTURE CARS PTE LTD
Date of Inspection	8/11/2021
Time of Inspection	10:30 HRS
Vehicle Make	HONDA
Vehicle Model	FIT 1.3 BASIC
Vehicle Model Code	6BA-GR1
Engine Number	L13B1604297
Chassis Number	GR11103237
Motor Number (if any)	-
Odometer Reading	78 KM

Wheels	
Front Tyre Size	185/60R15
Rear Tyre Size	185/60R15

Lighting	Yes	No	Remarks
Auto Levelling System		X	
Front Fog Lamp		X	
Rear Fog Lamp		X	
Type of Low Beam	<input checked="" type="checkbox"/>	Halogen	<input type="checkbox"/> LED <input type="checkbox"/> HID
Type of High Beam	<input checked="" type="checkbox"/>	Halogen	<input type="checkbox"/> LED <input type="checkbox"/> HID

Others	Yes	No	Remarks
Sunroof / Moonroof (if any)		X	
Transmission Type		<input type="checkbox"/> Manual	<input checked="" type="checkbox"/> Automatic


## Vehicle Identification (VIN) Chassis Plate




## Chassis Number Stamping



## Engine Number Stamping



## Front View



Rear View




Right View



## Left View



## Engine Compartment




### Front Tyre Size




### Rear Tyre Size




## Instrument Panel



## Exhaust System




## Exhaust System



## Exhaust System



## Speedometer



## Odometer



## Vehicle Light Transmittance (VLT)

Windscreen VLT Reading: 85% (front)



Windscreen VLT Reading: 32% (rear)



### Front Windows VLT Reading: 78% (left)



### Front Windows VLT Reading: 78% (right)



### Rear Windows VLT Reading: 31% (left)



### Rear Windows VLT Reading: 29% (right)



### Front Quarter Glass VLT Reading: 78 % (Left)



### Front Quarter Glass VLT Reading: 76% (Right)



### Rear Quarter Glass VLT Reading: 33% (Left)



### Rear Quarter Glass VLT Reading: 33% (Right)





**Section B: Observation**

**Section C: Undertaking by Authorised Inspectors**

We, hereby, verify that we have checked the above-mentioned vehicle on 08/11/21 (date)  
and correctly recorded the technical information on this form.

1) Inspector's Name & Signature: Ho Leong Chuan

(with company endorsement)


2) Inspector's Name & Signature: K.K.Lau

MSC,B.ENG(HONS),PE(USA)

(with company endorsement)