



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### TAX INVOICE

VENTURE CARS PTE LTD

33 UBI AVENUE 3  
#01-47/48 VERTEX  
SINGAPORE 408868

INV No. AC2107705

INV Date 09/11/2021

Reference CS5/TP21011370/Cq

Code TP534

### PROFESSIONAL SERVICE FEE

Vehicle No. GR11103551

Insured Veh.

Claim No. GR11103551

Policy No.

Accident Date

Inspection Date

| Description                                    | Total        |
|------------------------------------------------|--------------|
| On-Site Inspection for Parallel Import Vehicle | 75.00        |
| <b>Subtotal</b>                                | <b>75.00</b> |
| <b>GST (7%)</b>                                | <b>5.25</b>  |
| <b>Grand Total</b>                             | <b>80.25</b> |

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd

**FWL**



## INSPECTION CHECKLIST

Reference no: CS5/TP21011370/Cq

### Section A: Vehicle Check


|                       |                             |
|-----------------------|-----------------------------|
| <b>Applicant</b>      | <b>VENTURE CARS PTE LTD</b> |
| Date of Inspection    | 9/11/2021                   |
| Time of Inspection    | 11:30 HRS                   |
| Vehicle Make          | HONDA                       |
| Vehicle Model         | FIT 1.3 BASIC               |
| Vehicle Model Code    | 6BA-GR1                     |
| Engine Number         | L13B1604651                 |
| Chassis Number        | GR11103551                  |
| Motor Number (if any) | -                           |
| Odometer Reading      | 10 KM                       |

|                 |           |
|-----------------|-----------|
| <b>Wheels</b>   |           |
| Front Tyre Size | 185/60R15 |
| Rear Tyre Size  | 185/60R15 |

| Lighting              | Yes                                         | No                           | Remarks                      |
|-----------------------|---------------------------------------------|------------------------------|------------------------------|
| Auto Levelling System |                                             | X                            |                              |
| Front Fog Lamp        |                                             | X                            |                              |
| Rear Fog Lamp         |                                             | X                            |                              |
| Type of Low Beam      | <input checked="" type="checkbox"/> Halogen | <input type="checkbox"/> LED | <input type="checkbox"/> HID |
| Type of High Beam     | <input checked="" type="checkbox"/> Halogen | <input type="checkbox"/> LED | <input type="checkbox"/> HID |

| Others                      | Yes                             | No                                            | Remarks |
|-----------------------------|---------------------------------|-----------------------------------------------|---------|
| Sunroof / Moonroof (if any) |                                 | X                                             |         |
| Transmission Type           | <input type="checkbox"/> Manual | <input checked="" type="checkbox"/> Automatic |         |

## Vehicle Identification (VIN) Chassis Plate



## Chassis Number Stamping




## Engine Number Stamping



Front View



### Rear View



### Right View



### Left View



### Engine Compartment



## Front Tyre Size




## Rear Tyre Size



## Instrument Panel



## Exhaust System




## Exhaust System



## Exhaust System



## Speedometer



## Odometer



## Vehicle Light Transmittance (VLT)

Windscreen VLT Reading: 84% (front)




Windscreen VLT Reading: 32% (rear)




## Front Windows VLT Reading: 77% (left)



## Front Windows VLT Reading: 77% (right)



### Rear Windows VLT Reading: 30% (left)



### Rear Windows VLT Reading: 29% (right)



### Front Quarter Glass VLT Reading: 77 % (Left)



### Front Quarter Glass VLT Reading: 76% (Right)



## Rear Quarter Glass VLT Reading: 33% (Left)



## Rear Quarter Glass VLT Reading: 33% (Right)





**Section B: Observation**

**Section C: Undertaking by Authorised Inspectors**

We, hereby, verify that we have checked the above-mentioned vehicle on 09/11/21 (date)  
and correctly recorded the technical information on this form.

1) Inspector's Name & Signature: Ho Leong Chuan

(with company endorsement)



2) Inspector's Name & Signature: K.K.Lau  
MSc,B.ENG(HONS),PE(USA)

(with company endorsement)

