

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

VENTURE CARS PTE LTD

33 UBI AVENUE 3
#01-47/48 VERTEX
SINGAPORE 408868

INV No. AC2107709

INV Date 09/11/2021

Reference CS5/TP21011372/Cq

Code TP534

PROFESSIONAL SERVICE FEE

Vehicle No. GR11103660

Insured Veh.

Claim No. GR11103660

Policy No.

Accident Date

Inspection Date

Description	Total
On-Site Inspection for Parallel Import Vehicle	75.00
Subtotal	75.00
GST (7%)	5.25
Grand Total	80.25

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

FWL

INSPECTION CHECKLIST

Reference no: CS5/TP21011372/Cq

Section A: Vehicle Check


Applicant	VENTURE CARS PTE LTD
Date of Inspection	9/11/2021
Time of Inspection	13:30 HRS
Vehicle Make	HONDA
Vehicle Model	FIT 1.3 BASIC
Vehicle Model Code	6BA-GR1
Engine Number	L13B1604765
Chassis Number	GR11103660
Motor Number (if any)	-
Odometer Reading	12 KM

Wheels	
Front Tyre Size	185/60R15
Rear Tyre Size	185/60R15

Lighting	Yes	No	Remarks
Auto Levelling System		X	
Front Fog Lamp		X	
Rear Fog Lamp		X	
Type of Low Beam	☒ Halogen	☐ LED	☐ HID
Type of High Beam	☒ Halogen	☐ LED	☐ HID

Others	Yes	No	Remarks
Sunroof / Moonroof (if any)		X	
Transmission Type	☐ Manual	☒ Automatic	

Vehicle Identification (VIN) Chassis Plate




Chassis Number Stamping



Engine Number Stamping



Front View



Rear View




Right View




Left View



Engine Compartment




Front Tyre Size



Rear Tyre Size



Instrument Panel



Exhaust System




Exhaust System



Exhaust System



Speedometer



Odometer




Vehicle Light Transmittance (VLT)

Windscreen VLT Reading: 84% (front)



Windscreen VLT Reading: 32% (rear)



Front Windows VLT Reading: 77% (left)



Front Windows VLT Reading: 76% (right)



Rear Windows VLT Reading: 30% (left)



Rear Windows VLT Reading: 29% (right)




Front Quarter Glass VLT Reading: 77 % (Left)



Front Quarter Glass VLT Reading: 76% (Right)



Rear Quarter Glass VLT Reading: 32% (Left)



Rear Quarter Glass VLT Reading: 33% (Right)





Section B: Observation

Section C: Undertaking by Authorised Inspectors

We, hereby, verify that we have checked the above-mentioned vehicle on 09/11/21 (date)
and correctly recorded the technical information on this form.

1) Inspector's Name & Signature: Ho Leong Chuan

(with company endorsement)




2) Inspector's Name & Signature: K.K.Lau
MSc,B.ENG(HONS),PE(USA)

(with company endorsement)