LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG21011374/VVF3E2

18/11/2021 Date:

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1900131375 **Claimant Vehicle**

SLE5140C Insured Vehicle No: SMN940J No:

Date of Loss: 02/11/2021 Nature of Claim: TP Claim No: 9223050517SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLE5140C**

Make & Model: NISSAN LATIO, 1.5 L T (A) HR15196530A Engine No:

Reg. Date: 28/06/2008 (Man. Year: 2007) Chassis No: JN1BAAC11Z0006656

White Colour: Odometer: 133750 km

Engine Capacity: 1498 cc Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Engine Modification: Pre-accident Condition: Yes No

CONDITION OF TYRES

Front Tyre Size: 185/65 R15 Rear Tyre Size: 185/65 R15 Front Left Side: Rear Left Side: Hankook 5 mm Hankook 5 mm Front Right Side: Hankook 5 mm Rear Right Side: Hankook 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 08/11/2021

Cheng Chuan Motor Servics (HQ)

BLK 2 KAKI BUKIT AVENUE 2, #02-31/#02-26 Date Inspected: 09/11/2021 Inspected At: **AUTO HUB**

Singapore 417921

Estimated Period of Repair: 4.0 days

Adjuster: Thevan Thomas Karthikesavan **VERON CHEN** Manager:

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

MARKET VALUE: \$36,000.00 (EST)

REPAIR DETAILS

Recommended Parts

No.	Qty Part No.	Particulars	Condition	Repairer's	Amount
1	1	*REAR BUMPER	Deformed	0.00 F	*- F
2	1	*REAR BUMPER LOWER	Cut	0.00 F	*-F
3	1	*REAR BUMPER SIDE RETAINER	Necessary	0.00 F	*-F
4	1	*REAR BUMPER SPONGE	Bent	0.00 F	*-F
5	1	*REVERSE SENSOR	Cut	0.00 F	*-F
6	1	*REAR END PANEL	Repair	0.00 F	*-F
7	1	*REAR END PANEL TOP GARNISH	Cracked	0.00 F	*-F
8	1	*REAR RH TAILLAMP	Cut	0.00 F	*-F
9	1	*BOOTLID LOCK	Bent	0.00 F	*-F
10	1	*BOOTLID RUBBER	Cut	0.00 F	*- F
F=Fra	anchise part.				
			Total Parts (S\$)	0.00	0.00
		Report was unsubmitted du	uring this print-out.		

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >