

ASS. REC. BY:

REF:

CS/CT121011386/Tiny3

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: 470K

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: 4MP322SK Yr Regn: 2019 Sep

Type: M/Gar / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda Fit 1.3 C.C. 1317Colour: Yellow A/C: Insured / Std / NI / NASp. Reading: 113535 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: GK 3135157-1Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 185/60R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front _____ Rear _____

R/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. _____ D.O.I. 10/11/21Survey held at J.E.W Auto.

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Frt + N/S, U/C

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Date/Time, File Pass to?

1) _____
Date/Time, File Return to?

2) _____

Rep. Format: _____

Lump Sum / L.B.A. ()

☐ : Preli. Report☐ : Final Report

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee: _____

Transportation: _____

____ S + RS ____ SI

Photos

Others

TOTAL



Estimation

Date 07-11-21
Vehicle SMP 3225 K
Make/Model HONDA FIT
Chassis No. GK31351521

KK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

No.	Description	Unit	Unit Price	Amount
	Parts Replacment			
1	FRONT BONNET HINGE SET	2	\$ 55.00	\$ Rp 110.00
2	FRONT BONNET LOCK	1	\$ 95.00	\$ X 95.00
3	FRONT HEADLAMP L+R	2	\$ 1,197.00	SRHX LHcy 2,394.00
4	FRONT HEADLAMP LOWER BRACKET L+R	2	\$ 48.00	SRHX LHcy 96.00
5	FRONT GRILLE TOP CHROME	1	\$ 278.00	\$? 278.00
6	FRONT GRILLE LOWER CHROME	1	\$ 228.00	\$ cut 228.00
7	FRONT GRILLE CENTER ASSY	1	\$ 285.00	\$ cut 285.00
8	FRONT BUMPER	1	\$ 508.00	\$ de 508.00
9	FRONT BUMPER TOW COVER	1	\$ 55.00	\$ de 55.00
10	FRONT BUMPER RETAINER L+R	2	\$ 25.00	SRHX LHcy 50.00
11	FRONT BUMPER REINFORCEMENT BAR	1	\$ 299.00	\$ ht 299.00
12	FRONT BUMPER UNDERCOVER	1	\$ 138.00	\$? 138.00
13	FRONT BUMPER FOG LAMP GARNISH L+R	2	\$ 98.00	SRHX LHcy 196.00
14	FRONT BUMPER GRILLE	1		\$? -
15	FRONT BUMPER GRILLE LOWER	1	\$ 185.00	\$? 185.00
16	FRONT FENDER LH	1	\$ 456.00	\$ ht 456.00
17	FRONT FENDER INNER PANEL LH	1		\$ Rp -
18	FRONT FENDER RH	1	REPAIR	REPAIR
19	FRONT FENDER COWLING LH	1	\$ 108.00	\$ de 108.00
20	FRONT FENDER QUARTER GLASS MOULDING LH	1	\$ 148.00	\$ X 148.00
21	FRONT DOOR LH	1	REPAIR	REPAIR
22	FRONT DOOR SIDE MIRROR ASSY LH	1	\$ 510.00	\$ X 510.00
23	FRONT SUPPORT PANEL	1	\$ 510.00	\$ Rx 510.00
24	FRONT SUPPORT PANEL TOP GARNISH	1	\$ 32.00	\$ X 32.00
25	FRONT SUPPORT PANEL AIR GUIDE L+R	2	\$ 58.00	SRHX LHcy 116.00
26	FRONT AIR CON CONDENSOR	1	\$ 710.00	\$? 710.00
27	HIGH PRESSURE HOSE	1	\$ 190.00	\$? 190.00
28	LOWER PRESSURE HOSE	1	\$ 175.00	\$? 175.00
29	RADIATOR	1	\$ 1,187.00	\$ X 1,187.00
30	RADIATOR TOP HOSE	1	\$ 188.00	\$ X 188.00
31	RADIATOR BOTTOM HOSE	1	\$ 190.00	\$ X 190.00
32	RADIATOR FAN COWLING	1	\$ 90.00	\$ X 90.00
33	RADIATOR FAN BLADE	1	\$ 60.00	\$ X 60.00
34	RADIATOR FAN MOTOR	1	\$ 292.00	\$ X 292.00
35	FRONT HORN L+R	2	\$ 86.00	\$ A 172.00
36	FRONT ABSRBER LH	1	\$ 251.00	\$ X 251.00
37	FRONT LOWER ARM LH	1	\$ 198.00	\$ X 198.00

38	FRONT KNUCKLE ARM LH	1	\$	286.00	\$ 7	286.00
39	FRONT KNUCKLE BEARING LH	1	\$	115.00	\$ 7	115.00
40	FRONT BEARING HUB LH	1	\$	141.00	\$ X	141.00
					\$	-
					\$	-
					\$	-
					\$	-
					\$	-
					\$	-
					\$	-
					\$	-
					\$	-
				Total	\$	11,042.00
				Less 20%	\$	2,208.40
				Total	\$	8,833.60

S/Nett Items						
1	FRONT BONNET (CUSTOM CF W/ SLOTTED VENT)	1		2500	\$ One / 1000	2,500.00
2	FRONT BUMPER CLIPS	10		12	\$ 3 over	120.00
3	FRONT FENDER COWLING CLIPS	10		12	\$ 10 per	120.00
4	FRONT AIR CON GAS	1		150	\$ 1,000	150.00
5	FRONT RADIATOR COOLANT	1		150	\$ X	150.00
6	FRONT BUMPER LOWER LIP	1		1800	\$ cut 500	1,800.00
7	FRONT TYRE LH	1		800	\$ cut 200	800.00
8	FRONT RIM LH	1		1200	\$ cut 600	1,200.00
				Total	\$	6,840.00

LABOUR						
1	PANEL BEATING ON AFFECTED AREAS	1		1600	\$ 700	1,600.00
2	SPRAY PAINT ON AFFECTED AREAS	1		1600	\$ 700	1,600.00
3	TO RNR FRONT WINDSCREEN	1		300	\$ X	300.00
4	TO CHECK WIRING AND HEADLAMP FOCUS	1		150	\$ 30	150.00
5	TO CHECK WHEEL ALIGNMENT AND ADJUST	1		200	\$ 80	200.00
6	TO RNR UNDERCARRIAGE	1		250	\$ 150? plus	250.00
7	TO CHECK WHEEL BALANCING	1		200	\$ 30	200.00
8	TO RNR FRONT AIR CON CONDENSOR AND TOP UP GAS	1		300	\$ X	300.00
9	TO RNR FRONT RADIATOR	1		250	\$ X	250.00
10	TO PERFORM DIAGNOSTIC AND CLEAR FAULTS	1		600	\$ X	600.00
11	TO RNR REAR TAILGATE MECHANISM	1		300	\$ X	300.00
12	TO RNR REAR FRONT DOOR MECHANISM	1		120	\$ X	120.00
13	TO PERFORM RUST PROOFING	1		200	\$ 20	200.00
14	TO RNR HORN AND TEST FUNCTION	1		150	\$ X	150.00
15	TO REPAIR FRONT LH CHASSIS	1		1200	\$ X	1,200.00

Total Labour	\$	7,420.00
Parts Replacement Amount	\$	15,673.60
Total Amount	\$	23,093.60

Taufiq 97495749
 WP 10/11/21 @ 4pm
 4/5 Resum after repair 5 days
 Taufiq@clkbank.com