

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC4/GRB21011394/AGS3Q2**Date:** 14/02/2022REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D21MFL0000447  
**Claimant Vehicle No :** GBL2998X **Insured Vehicle No :** SMZ3978T  
 Date of Loss: 05/11/2021 Nature of Claim: TP Claim No: MFL2021D0004863

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBL2998X**  
 Make & Model: NISSAN NV200, 1.5 (A) Engine No: HR16180848D  
 Reg. Date: 05/05/2021 (Man. Year: 2020) Chassis No: VM20163597  
 Colour: Grey Odometer: 11258 km  
 Engine Capacity: 1597 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 165/80 R14 Rear Tyre Size: 165/80 R14  
 Front Left Side: Toyo 6 mm Rear Left Side: Toyo 6 mm  
 Front Right Side: Toyo 6 mm Rear Right Side: Toyo 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	13,391.14	5,271.85	8,119.29	60.63
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,615.00	2,120.00	1,495.00	41.36
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>17,006.14</b>	<b>7,391.85</b>	<b>9,614.29</b>	<b>56.53</b>
<b>+ GST 7.00/7.00% (S\$)</b>	1,190.43	517.43	673.00	56.53
<b>Nett Amount (S\$)</b>	<b>18,196.57</b>	<b>7,909.28</b>	<b>10,287.29</b>	<b>56.53</b>
<b>+ Car Rental (11.0 x S\$74.90/day) (S\$)</b>		823.90		
<b>+ Doc/Search Fee (S\$)</b>		7.45		
<b>Nett Liability (S\$)</b>		<b>8,740.63</b>		
<b>Global Sum Settlement (S\$)</b>		<b>8,700.00</b>		

INSPECTION

Date of Assignment: 08/11/2021  
 Date Inspected: 09/11/2021 Inspected At: Sk Automobile Pte Ltd  
 8 Kaki Bukit Ave 4, #08-46 Premier @ Kaki Bukit  
 Singapore 415875  
 Estimated Period of Repair: 8.0 days

**Adjuster:** ADRIAN LING**Manager:** Chong Pui Lin

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	(Last Synchronised: 25 Jan 2022)	
<b>Parts:</b>	N/A	NISSAN NV200 1.5 (A) (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for GBL2998X)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE	Distorted	1,635.00 FL	*1,635.00 FL
2	1		*REAR TAILGATE LOGO EMBLEM	Necessary	64.90 FL	*64.90 FL
3	1		*REAR TAILGATE NV200 EMBLEM	Necessary	94.40 FL	*94.40 FL
4	1		*REAR TAILGATE VANETTE EMBLEM	Necessary	64.90 FL	*64.90 FL
5	1		*REAR TAILGATE WIPER ARM	Not Necessary	83.30 FL	*- FL
6	1		*REAR TAILGATE WIPER MOTOR	Not Necessary	212.20 FL	*- FL
7	1		*REAR TAILGATE OUTER GARNISH	Not Necessary	363.00 FL	*- FL
8	1		*REAR TAILGATE INNER UPHOLSTERY TRIM BOARD	Deformed	180.50 FL	*180.50 FL
9	1		*REAR TAILGATE INNER LOCK ACTUATOR	Damaged	352.00 FL	*352.00 FL
10	1		*REAR TAILGATE MECHANISM LOCK	Damaged	287.10 FL	*287.10 FL
11	1		*REAR TAILGATE WEATHERSTRIP	Cut	88.40 FL	*88.40 FL
12	1		*REAR TAILLAMP LH/RH	N/S Cut	235.40 FL	*235.40 FL
13	2		*REAR FENDER LH/RH	Repair	2,879.40 FL	*- FL
14	1		*REAR BUMPER	Deformed	481.10 FL	*481.10 FL
15	2		*REAR BUMPER SIDE RETAINER LH/RH	Not Necessary	74.40 FL	*- FL
16	1		*REAR BUMPER TOW HOOK COVER	Not Necessary	18.10 FL	*- FL
17	1		*REAR END PANEL OUTER	Dented	115.20 FL	*115.20 FL
18	1		*REAR END PANEL INNER	Dented	576.00 FL	*576.00 FL
19	1		*REAR END PANEL INNER TOP GARNISH	Deformed	76.60 FL	*76.60 FL
20	1		*REAR END PANEL TAILGATE LOCK STRIKER	Not Necessary	35.80 FL	*- FL
21	1		*REAR FLOOR PANEL	Repair	1,374.60 FL	*- FL
22	1		*REAR FLOOR PANEL TOP CARMAT	Not Necessary	438.00 FL	*- FL
23	1		*SPARE TYRE BRACKET	Not Necessary	251.10 FL	*- FL
24	1		*SET SPARE TYRE SCREW LOCK	Not Necessary	108.20 FL	*- FL
25	1		*REAR BUMPER SPONGE	Cracked	95.00 FL	*95.00 FL
26	1		*SET REAR TAILGATE WINDSCREEN SEALANT WITH PRIMER	Necessary	100.00 FS	*60.00 FS
27	1		*REAR TAILGATE ADVERTISEMENT AND ART WORK STICKER	Necessary	550.00 FS	*380.00 FS
28	1		*REAR TAILGATE 70KM/H STICKER	Necessary	50.00 FS	*15.00 FS
29	1		*REAR TAILGATE 6 PAX STICKER	Necessary	50.00 FS	*15.00 FS
30	1		*SET REAR TAILGATE NUMBER PLATE WITH CASING	Dented	85.00 FS	*50.00 FS
31	1		*SET REAR TAILGATE OUTER GARNISH CLIPS	Necessary	50.00 FS	*20.00 FS
32	1		*SET REAR TAILGATE REVERSE CAMERA	Not Necessary	580.00 FS	*- FS
33	1		*SET REAR TAILGATE INNER UPHOLSTERY TRIM BOARD CLIPS	Necessary	60.00 FS	*30.00 FS
34	1		*REAR TAILLAMP CLIPS SET LH/RH	Necessary	40.00 FS	*10.00 FS
35	1		*REAR FENDER ADVERTISEMENT AND ART WORKS STICKER LH/RH	O/S Necessary	1,760.00 FS	*400.00 FS
36	1		*REAR BUMPER COMPANY EMAIL STICKER	Necessary	250.00 FS	*80.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
37	1		*SET REAR BUMPER CLIPS	Necessary	80.00 FS	*30.00 FS
38	1		*SET REAR BUMPER REVERSE SENSOR	Damaged	280.00 FS	*200.00 FS
39	1		*REAR END PANEL SEALANT	Necessary	100.00 FS	*60.00 FS
40	1		*SET REAR END PANEL INNER TOP GARNISH CLIPS	Necessary	40.00 FS	*10.00 FS
41	1		*REAR FLOOR PANEL SEALANT	Not Necessary	150.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>14,409.60</b>	<b>5,706.50</b>
<b>- List Item Discount on L Items 10.00/10.00% (\$\$)</b>	1,018.46	434.65
<b>Total Parts (\$\$)</b>	<b>13,391.14</b>	<b>5,271.85</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO DISMANTLE & REPLACED WITH PANEL BEATING ALL THE ACCIDENT PORTION	New	2,000.00	1,000.00
2	TO SPRAY PAINTING ALL THE ACCIDENT PORTION & POLISHING AFFECTED AREA	New	1,000.00	900.00
3	TO APPLY ANTI-RUST & TUFF KOTE	New	125.00	60.00
4	TO PERFORM LIGHTING & WIRING CHECK	New	80.00	30.00
5	TO DISMANTLE & REPLACED REAR BUMPER REVERSE SENSOR WITH DISTANCE SETTING	New	80.00	50.00
6	TO DISMANTLE & REINSTALL INTERIOR CARPET WITH OTHER ATTACHMENT PARTS COMPONENT TO FACILITATE REPAIR	New	250.00	80.00
7	TO PERFORM CONDUCT WATER LEAKAGE TEST OF ACCIDENT PORTION	New	80.00	0.00
<b>Gross Labour Cost (\$\$)</b>			<b>3,615.00</b>	<b>2,120.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >