

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21011399/UEA3Q2**Date:** 25/02/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	0999993661
Claimant Vehicle No :	SJV9925M	Insured Vehicle No :	SMR9046K
Date of Loss:	15/10/2021	Nature of Claim:	TP
		Claim No:	8078242928SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJV9925M	Engine No:	3ZZ4949187
Make & Model:	TOYOTA COROLLA ALTIS, 1.6 (A)	Chassis No:	MR053ZEE106160834
Reg. Date:	26/02/2010 (Man. Year: 2009)	Odometer:	248656 km
Colour:	Beige		
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Tourador 6 mm	Rear Left Side:	Tourador 6 mm
Front Right Side:	Tourador 6 mm	Rear Right Side:	Tourador 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,435.12	827.17	607.95	42.36
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,520.00	720.00	800.00	52.63
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	2,955.12	1,547.17	1,407.95	47.64
Approved Total (Overridden) (S\$)		1,200.00		
(S\$)	2,955.12	1,200.00	1,755.12	59.39
+ GST 7.00/7.00% (S\$)	206.86	84.00	122.86	59.39
Nett Amount (S\$)	3,161.98	1,284.00	1,877.98	59.39
+ Car Rental (3.0 x S\$100.00/day) (S\$)		300.00		
+ Doc/Search Fee (S\$)		36.45		
Nett Liability (S\$)		1,620.45		
Global Sum Settlement (S\$)		1,620.00		

INSPECTION

Date of Assignment:	08/11/2021		
Date Inspected:	10/11/2021	Inspected At:	Focus Auto Pte Ltd (HQ) 1 Kaki Bukit Ave 6, #02-48/50 Autobay Singapore 417883
Estimated Period of Repair:	3.0 days		

Adjuster: MARCUS CHUA**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER -R/H	Repair	651.20 FL	*- FL
2	1		*FRONT FENDER DUST COVER-R/H	Not Necessary	126.40 FL	*- FL
3	6		*FRONT FENDER DUST COVER CLIP-R/H	Not Necessary	33.00 FL	*- FL
4	1		*FRONT HEADLAMP -R/H	Cracked	543.90 FL	*543.90 FL
5	1		*FRONT BUMPER	Deformed / Torn	481.60 FL	*481.60 FL
6	1		*FRONT BUMPER SIDE RETAINER -R/H	Bent	51.60 FL	*51.60 FL
7	1		*SET FRONT BUMPER CLIP	Necessary	25.80 FL	*25.80 FL
					Sub Total (\$)	1,913.50
					- List Item Discount on L Items 25.00/25.00% (\$)	478.38
					Total Parts (\$)	1,435.12

F=Franchise part. L=ListItemDisc.

1,102.90

275.73

827.17

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	750.00	300.00
2	CHECK WIRING	New	60.00	20.00
3	RUST PROOFING	New	60.00	0.00
4	SPRAY PAINTING	New	650.00	400.00
Gross Labour Cost (\$\$)			1,520.00	720.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >