

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/MSG21011406/ETF3N2**Date:** 13/05/2022**REFERENCE**

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	1001285350
<b>Claimant Vehicle No :</b>	SJJ9943Z	<b>Insured Vehicle No :</b>	SJM5617B
Date of Loss:	03/11/2021	Nature of Claim:	TP
		Claim No:	265054

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>SJJ9943Z</b>	Engine No:	R18A1786254
Make & Model:	HONDA STREAM, 1.8 L RSZ (A)	Chassis No:	RN61077569
Reg. Date:	30/09/2008 (Man. Year: 2008)	Odometer:	373130 km
Colour:	White		
Engine Capacity:	1799 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size:	195/50R16	Rear Tyre Size:	195/50R16
Front Left Side:	Bridgestone 4 mm	Rear Left Side:	Bridgestone 4 mm
Front Right Side:	Bridgestone 4 mm	Rear Right Side:	Bridgestone 4 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	9,424.16	4,382.00	5,042.16	53.50
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,670.00	1,820.00	850.00	31.84
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>12,094.16</b>	<b>6,202.00</b>	<b>5,892.16</b>	<b>48.72</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>4,150.00</b>		
<b>Nett Amount (S\$)</b>	<b>12,094.16</b>	<b>4,150.00</b>	<b>7,944.16</b>	<b>65.69</b>

**INSPECTION**

Date of Assignment:	09/11/2021		
Date Inspected:	09/11/2021	Inspected At:	399J WOODLANDS ROAD SINGAPORE 678008 REPAIRER: CAR PRO AUTO
Estimated Period of Repair:	5.0 days		

**Adjuster:** CHEN TSUE YEE**Manager:** DENISE TAY KWEE CHENG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

**REPAIR DETAILS****Reference**

<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 13 May 2022)
<b>Parts:</b> M1-MPV	HONDA STREAM 1.8 L RSZ (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SJJ9943Z)
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.

**Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Dented	620.00 FL	*620.00 FL
2	2		*REAR BUMPER SIDE RETAINER	Broken	60.00 FL	*60.00 FL
3	2		*REAR BUMPER BRACKET	Not Necessary	48.00 FL	*- FL
4	1		*SET REAR BUMPER CLIPS	Necessary	35.00 FL	*30.00 FL
5	1		*TAIL LAMP LH	Cut	800.00 FL	*352.00 FL
6	2		*SETS TAIL LAMP CLIPS	Not Necessary	42.00 FL	*- FL
7	1		*TAIL GATE	Dented	1,050.00 FL	*983.00 FL
8	1		*TAIL GATE INNER LOCK	Bent	185.00 FL	*185.00 FL
9	1		*TAIL GATE LOCK STRIKER	Not Necessary	35.00 FL	*- FL
10	1		*TAIL GATE WIPER ARM	Not Necessary	60.00 FL	*- FL
11	1		*TAIL GATE WIPER BLADE	Not Necessary	55.00 FL	*- FL
12	1		*TAIL GATE WIPER MOTOR	Not Necessary	288.00 FL	*- FL
13	1		*TAIL GATE WEATHERSTRIP	Torn	185.00 FL	*185.00 FL
14	1		*TAIL GATE HONDA LOGO	Not Necessary	85.00 FL	*- FL
15	1		*TAIL GATE STREAM LOGO	Necessary	85.00 FL	*58.00 FL
16	1		*TAIL GATE RSZ LOGO EMBLEM	Necessary	70.00 FL	*60.00 FL
17	1		*TAIL GATE SHOCK ABSORBER LH	Not Necessary	120.00 FL	*- FL
18	1		*TAIL GATE STOPPER	Not Necessary	10.20 FL	*- FL
19	1		*TAIL GATE INNER TRIM BOARD	Broken	280.00 FL	*280.00 FL
20	1		*TAIL GATE LOWER PULL HANDLE	Not Necessary	55.00 FL	*- FL
21	1		*TAIL GATE CENTRE GARNISH	Not Necessary	218.00 FL	*- FL
22	1		*REAR END PANEL	Dented	385.00 FL	*306.00 FL
23	1		*REAR END PANEL TOP GARNISH	Broken	180.00 FL	*130.00 FL
24	1		*REAR END PANEL TOP GARNISH CLIPS	Necessary	20.00 FL	*10.00 FL
25	1		*SPARE TYRE PANEL	Repair	698.00 FL	*- FL
26	2		*SPARE TYRE PANEL BOARD	Not Necessary	558.00 FL	*- FL
27	1		*REAR WINDSCREEN	Not Necessary	1,080.00 FL	*- FL
28	2		*REAR WINDSCREEN GLASS MOULDING	Necessary	65.00 FL	*65.00 FL
29	2		*REAR WINDSCREEN INNER SEAL	Not Necessary	30.00 FL	*- FL
30	1		*REAR CHASSIS FRAME	Not Necessary	350.00 FL	*- FL
31	2		*REAR FENDER INNER TRIM LH & RH	Broken	860.00 FL	*768.00 FL
32	2		*SET REAR FENDER INNER TRIM CLIPS LH & RH	Necessary	70.00 FL	*20.00 FL
33	1		*EXHAUST MOUNTING	Not Necessary	93.00 FL	*- FL
34	1		*TOWING COVER	Crushed	95.00 FL	*28.00 FL
35	2		*CARPLATE LAMPS	Not Necessary	110.00 FL	*- FL
36	1		*LTA COMPLIANT WHOLE EXHAUST ASSY	Bent	1,500.00 FS	*800.00 FS
37	1		*WINDSCREEN SEALANT	Necessary	60.00 FS	*40.00 FS
38	1		*REAR END PANEL SEALANT	Necessary	60.00 FS	*30.00 FS
39	4		*REVERSE SENSOR	Shorted	200.00 FS	*200.00 FS
40	1		*NUMBER PLATE W CASING	Not Necessary	50.00 FS	*- FS
41	1		*REVERSE CAMERA	Not Necessary	250.00 FS	*- FS
42	1		*INSULATOR PAD	Not Necessary	120.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$)</b>	<b>11,220.20</b>	<b>5,210.00</b>
<b>- List Item Discount on L Items 20.00/20.00% (\$)</b>	1,796.04	828.00

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
					<b>Total Parts (\$)</b>	<b>9,424.16</b>	<b>4,382.00</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	SPRAYING OF AFFECTED AREAS,BOOTLID/BUMPER/END PANEL/SPARE TYRE PANEL/FENDERS	New	800.00	800.00
2	CARRY OUT BODY CAVITY PRESERVATION	New	100.00	30.00
3	TO REMOVE AND REPLACED DAMAGED PARTS INCLUDING STRAIGHTENING AND REPOSITIONING REPLACEMENT PARTS & PANEL BEAT,REAR FENDER LH/RH,BOOTLID,END PANEL ETC	New	800.00	600.00
4	CHECK WIRING	New	50.00	30.00
5	REMOVE & REINSTALL REAR WINDSCREEN	New	150.00	120.00
6	REMOVE & REFIX BOOTLID COMPONENT	New	80.00	50.00
7	REMOVE & REINSTALL REVERSE SENSOR	New	60.00	30.00
8	REMOVE & REINSTALL REAR BOOT UPHOLSTERY	New	80.00	50.00
9	REMOVE & REFIX EXHAUST	New	100.00	80.00
10	TO STRAIGHTEN REAR CHASSIC MEMBER	New	250.00	0.00
11	REMOVE & REFIX REAR SEATS AND CUSHION	New	120.00	0.00
12	REMOVE & REINSTALL REVERSE CAMERA	New	80.00	30.00
<b>Gross Labour Cost (\$\$)</b>			<b>2,670.00</b>	<b>1,820.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >