

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/AIG21011409/KTF3N2**Date:** 25/11/2021REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800119696
Claimant Vehicle No :	SJV1413B	Insured Vehicle No :	SJK9352Z
Date of Loss:	06/11/2021	Nature of Claim:	TP
		Claim No:	8522556026SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJV1413B		
Make & Model:	KIA CERATO FORTE, 1.6 SX AT ABS D/AB 2WD 4DR (A)	Engine No:	G4FC9H341234
Reg. Date:	13/01/2010 (Man. Year: 2009)	Chassis No:	KNAFW411MA5174972
Colour:	Metallic Grey	Odometer:	279400 km
Engine Capacity:	1591 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Kumho 8 mm	Rear Left Side:	Kumho 6 mm
Front Right Side:	Kumho 8 mm	Rear Right Side:	Kumho 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,564.49	3,227.70	336.79	9.45
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,490.00	1,330.00	160.00	10.74
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,054.49	4,557.70	496.79	9.83
Approved Total (Overridden) (S\$)		3,600.00		
(S\$)	5,054.49	3,600.00	1,454.49	28.78
+ GST 7.00/7.00% (S\$)	353.81	252.00	101.81	28.78
Nett Amount (S\$)	5,408.30	3,852.00	1,556.30	28.78

INSPECTION

Date of Assignment:	09/11/2021	
Date Inspected:	09/11/2021	Inspected At:
Estimated Period of Repair:	5.0 days	160 SIN MING DRIVE #06-20 SIN MING AUTOCITY SINGAPORE 575722 REPAIRER: RC AUTO

Adjuster: KENNETH KONG**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER	Bent	476.54 FL	*476.54 FL
2	1		*FRONT FENDER COWLING	Distorted	96.00 FL	*96.00 FL
3	1		*FRONT BUMPER	Bent	670.00 FL	*620.00 FL
4	1		*FRONT DOOR	Bent	980.00 FL	*852.00 FL
5	1		*FRONT DOOR STICKER	Necessary	68.00 FL	*68.00 FL
6	1		*FRONT ABSORBER	Bent	370.00 FL	*370.00 FL
7	1		*FRONT LOWER ARM	Distorted	460.00 FL	*374.90 FL
8	1		*FRONT KNUCKLE ARM	Bent	340.00 FL	*340.00 FL
9	1		*SPORTS RIM	Dented	450.00 FS	*350.00 FS
					Sub Total (\$\$)	3,910.54
					- List Item Discount on L Items 10.00/10.00% (\$\$)	346.05
					Total Parts (\$\$)	3,564.49

F=Franchise part. S=SpcNett. L=ListItemDisc.

3,547.44
319.74
3,227.70

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	WHEEL ALIGNMENT	New	60.00	60.00
2	TO RESPRAY JOB	New	500.00	500.00
3	TO RENEW UNDERCARRIAGE	New	250.00	200.00
4	TO CHECK WIRING	New	30.00	20.00
5	PANEL BEATING	New	650.00	550.00
Gross Labour Cost (\$)			1,490.00	1,330.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >