(08/11/13) wef ASS. REC. BY: Mages  REF: C5/7/2/	011.412/11+63
	GNMENT
Estimated Cost:  OD TP) WS / TP RES / OD RES / EVA / INV / MV  To Inspect Vehicle No:  at Workshop m/s  of  Insured:  Policy No.	Veh No: SMS S652 / Yr Regn: 30/9//9  Type: McCarl M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  Truck / Trailer or (1)  Make: Hong Shuttle Hybridec (4)  Colour Can A/C: Insured / Std / NI / NA  Sp.Reading 24536 (7/Radio: Insured / Std / NI / NA  Eng/No:  C/No: GP72004688
Claims No.  Sum Insured: Excess:  (Client's Record)  Make of Veh:	Gen. Cond: Good / Fair / Poor / Burnt Steering: Inorder / Jammed / Leaked / Burnt or Brake: Inorder / Jammed / Leaked / Burnt or Modi: Nil State / STD A/Rim or Tyre Size: F: / Pc//60 R / 5 ga en /s
(Policy Condition)  Remark: The veh had commenced its repair at the time of inspection.  Bal. or Market Value:  IDAC Accident Rport:  GIA / PR Seen:  Est. Repairs:  Jays Res.: Yes or No  Lum Sum:  CA / REV / REP. / 24 HRS  Vehicle: IN / OUT	R:  BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or  Front R/Bal. 7 mm R/Bal. 7 mm  L/Bal. 7 mm  D.O.A. 29/10/2/ D.O.I. 9/11/2/ Survey held at  Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or
Date: Person Contacted: LYA \$36039  Date / Time Action / Instruction Deploy  Alox NYUC JOSFIN  RED: 2079.52;40%	The U/C / Chassis frame / Body Structure affected due to collision.
1) : Final Report 2) : Add Fee Report Format :	Days Of Repair:    Resurvey No. of Trip:   Survey Fee:
Lump Sum / I.B.I: (\$	I I/Mookond (a)

BLUWEL RENT-A-CAR PTE LTD 1 KAKI BUKIT AVE 6 BLK C # 01-56 SINGAPORE 417883

## **VEHICLE No: SMP 5652Y**

1PC	REAR WINDSCREEN MOULDING	Nec		\$118.20
1PC	TAILGATE	カク		\$1,193.20
1PC	TAILGATE 'H' LOGO	Nec		\$38.00
1PC	TAILGATE 'SHUTTLE' EMBLEM	Nel		\$55.40
1PC	TAILGATE 'HYBRID' EMBLEM	Nec		\$58.20
1PC	TAILGATE INNER LOCK	su		\$256.40 X
1PC	REAR BUMPER	20/00		\$936.50
2PCS	REAR BUMPER SIDE RETAINERS @\$4	45.00 Nes		\$90.00
1PC	REAR END PANEL	R		\$561.00 🗡
				\$3,306.90
			LESS20%	\$2,429.52

1SET	REAR BUMPER REVERSE SENSOR	Should	\$280.00 200
1SET	REAR BUMPER CLIPS	ner	\$40.00
1PC	REAR WINDSCREEN SEALANT	re	\$50.00 <b>4</b> 0
1PC	REAR WINDSCREEN INNER SEAL	rei	\$50.00 40
1PC	REAR END PANEL SEALANT	NA	\$50.00 🗡

TO CHECK WIRING		\$50.00 20
TO DISMANTLE & REPLACED REAR REVERSE SENSOR		\$80.00
TO DISMANTLE & REFIX REAR WINDSCREEN		\$150.00 [20
TO DISMANTLE & REFIX TAILGATE MECHANISM		\$100.00 60
TO DISMANTLE & REFIX REAR CUSHION UPHOLSTERY		\$120.00 80
TO SPRAY RUST PROOFING		\$80.00 40
LABOUR FOR PANEL BEATING & REPLACED PARTS		\$800.00
TO PUTTY & SPRAY PAINTING		\$900.00 680
	TOTAL	\$5,179.52

LKK Auto Consultants hence notify the Repairer of the following:

- · To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- . No illegal modification(s) is allowed
- · Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

(600)

Not Arthurd New 3100 9/11/11 4/58 3100 3 days.