

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT						
	NTUC INCOME INSURANCE CO-OPERATIVE LTD			Ref:	CS/INC21011414/Aqf3s2	
	73 BRAS BASAH R #05-01 NTUC TRA 189556	ROAD DE UNION HOUSESINGAPORE		Date:	26/05/2022	
	ATTN: CHARLOTT	E CHEW		Code:	INC	
1.	Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SJZ 2023R	Veh. Inspected		SJQ 8677L	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	MT/1149500-002	Excess (\$)		0.00	
	Assign From	ANNIE KOH	Assign Date		09/11/2021	
2.	2. Vehicle Particulars & Condition					
	Make & Model	B.M.W. 320I	c.c		1995	
	Engine No.	HIDDEN	Year of Reg.		2008	
	Chassis No.	WBAPG56080NL23436	Colour		BLACK	
	Odometer	131948 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	GOOD				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	205/55 R16	PIRELLI		6 mm	
	L/H Front Tyre	205/55 R16	PIRELLI		6 mm	
	R/H Rear Tyre	205/55 R16	PIRELLI		6 mm	
	L/H Rear Tyre	205/55 R16	PIRELLI		6 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.					
	DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	28/10/2021	Inspect Date /	Time	09/11/2021 ( 11:15 AM )	
	Survey held at	CAS GARAGE PTE LTD				
		NO. 1 KAKI BUKIT AVE 6, #02-22 AUTOBAY 417883 KAKI BUKIT				
5a.	Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	Estimate Days of Repair					
	ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days					