



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLR 8012B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR BOOT LID	DENTED	896.20	896.20
1	REAR BOOT LID CENTRE MOULDING	NOT NECESSARY	215.30	-
1	REAR BOOT LID EMBLEM LOGO	NECESSARY	43.70	43.70
1	REAR BOOT LID AXIO LOGO	NECESSARY	43.55	43.55
1	REAR BOOT LID RH LOGO	NECESSARY	49.90	49.90
1	REAR BOOT LID NUMBER PLATE	NOT NECESSARY	50.00	-
2	REAR BOOT LID NUMBER PLATE LAMP @\$83.20	NOT NECESSARY	166.40	-
1	REAR BOOT LID INNER LOCK	DAMAGED	215.10	215.10
1	REAR BOOT LID INNER RUBBER	NOT NECESSARY	182.25	-
2	REAR TAIL LAMP @\$352.10	O/S CUT	704.20	352.10
4	REAR TAIL LAMP CLIPS @\$6.50	NECESSARY	26.00	10.00
1	REAR BUMPER	DEFORMED	625.00	625.00
8	REAR BUMPER CLIPS @\$6.50	NECESSARY	52.00	30.00
2	REAR BUMPER SIDE BRACKET @\$132.00	NOT NECESSARY	264.00	-
2	REAR BUMPER SIDE REFLECTOR @\$82.20	NOT NECESSARY	164.40	-
2	REAR BUMPER SIDE RETAINER @\$132.50	O/S DAMAGED	265.00	55.00
1	REAR BUMPER REINFORCEMENT	NOT NECESSARY	385.20	-
1	REAR EXHAUST ALUMINIUM COVER	NOT NECESSARY	187.45	-
1	REAR END PANEL	DENTED	521.00	521.00
1	REAR END PANEL TOP GARNISH	DEFORMED	185.20	185.20
1	REAR SPARE TYRE PANEL TOP COVER	NOT NECESSARY	289.95	-
1	REAR SPARE TYRE PANEL SEALANT	NOT NECESSARY	225.00	-
	LESS 25% DISCOUNT		-	-756.69
			5,756.80	2,270.06
<u>SPECIAL NETT ITEMS</u>				
1	REAR BUMPER REVERSE SENSOR (SN)	DAMAGED	350.00	200.00
			350.00	200.00
<u>LABOUR</u>				
	TO REMOVE & REFIX CUSHION.		120.00	60.00
	TO REMOVE & RE-FIX REVERSE SENSOR.		120.00	50.00

Report Ref No. CS/INC21011415/Atf3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REMOVE & REFIX REAR WINDSCREEN.	NOT NECESSARY	120.00	-
	GUM.	NOT NECESSARY	50.00	-
	TO CHECK WIRING.		60.00	30.00
	TUFF KOTE.		120.00	60.00
	PANEL BEATING.		800.00	700.00
	SPRAY PAINTING.		800.00	650.00
			2,190.00	1,550.00
GRAND TOTAL			8,296.80	4,020.06
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)				3,200.00

Report Ref No. CS/INC21011415/Atf3e2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.