



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKX 560T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BUMPER	BUCKLED / CRACKED	1,171.00	1,171.00
2	REAR BUMPER RETAINER	O/S DISTORTED	90.00	45.00
1	REAR BUMPER REFLECTOR RIGHT	SERVICEABLE	131.00	-
3	REAR BUMPER STICKER MOULDING	NECESSARY	225.00	225.00
1	REAR FENDER RIGHT	BENT	1,917.00	1,917.00
1	REAR FENDER TOP GARNISH RIGHT	SERVICEABLE	1,070.00	-
1	REAR RAIL RUNNER	SERVICEABLE	450.00	-
1	PETROL COVER	DENTED	234.00	201.00
1	TAIL LAMP	SERVICEABLE	1,118.00	-
1	WHEEL RIM	SERVICEABLE	1,033.00	-
1	QUARTER GLASS	SERVICEABLE	1,200.00	-
	LESS 20% DISCOUNT		-	-711.80
			8,639.00	2,847.20
	<u>LABOUR</u>			
	RUST PROOFING.		100.00	30.00
	PANEL BEATING.		1,200.00	700.00
	SPRAY PAINTING.		1,000.00	800.00
	TO REMOVE AND REFIT GLASS AND CUSHION.		500.00	200.00
			2,800.00	1,730.00
	GRAND TOTAL		11,439.00	4,577.20
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			3,600.00

Report Ref No. CS/AGI21011417/Kvf3n2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.