



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMS 8181D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	FRONT BUMPER	GRAZED / DEFORMED	2,192.42	1,973.18
1	FRONT BUMPER LOWER GRILLE	GRAZED	171.45	171.45
1	FRONT BUMPER LOWER GRILLE CHROME	MOUNTING BROKEN	200.31	200.31
1	FRONT BUMPER PARKING SENSOR LH	SERVICEABLE	202.75	-
1	FRONT BUMPER PARKING SENSOR OUTER LH	SERVICEABLE	202.75	-
1	FRONT BUMPER FOAM	BROKEN	265.93	265.93
1	FRONT BUMPER REINFORCEMENT	TO REPAIR SEE LABOUR	821.54	-
1	HEADLAMP ASSY LH	GRAZED	7,398.37	6,658.54
	LESS 10% DISCOUNT		-1,145.55	-926.95
			10,309.97	8,342.46
	<b><u>LABOUR</u></b>			
	LABOUR TO REPAIR & REPLACE DAMAGED PARTS.INCLUSIVE OF THE REPAIR OF FRONT BUMPER REINFORCEMENT.		500.00	200.00
	SPRAY PAINTING ON AFFECTED AREA.		500.00	200.00
	CHECK WIRING SYSTEM & REFOCUS HEADLAMP.		60.00	20.00
	TO DIAGNOSE & RECODING HEADLAMP SYSTEM.		420.00	150.00
			1,480.00	570.00
	<b>GRAND TOTAL</b>		<b>11,789.97</b>	<b>8,912.46</b>
	<b>RECOMMENDED COST OF REPAIRS</b>			<b>8,912.46</b>

Report Ref No. CS3/CTI21008475/Gucn2-1

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

ANG BRYAN TANI

Automotive Assessor / Investigator

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.