

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

|            |   | nale Des Experts En Automo                  |                | bile CS3/CTI21008475 |                        |            |
|------------|---|---|----------------|----------------------|------------------------|------------|
|            | CHINA TAIPING IN  |   | Ref:           | CC3/CT1210           | 00110/040              |            |
|            | 3 ANSON ROAD #<br>SPRINGLEAF TO   | 16-00<br>VERSINGAPORE 079909                |                | Date:                | 1 <del>2/00/2021</del> | 08.11.2021 |
|            |   |   |                | Code:                | CTI                    |            |
|            | Policy Particulars :- (THIRD PARTY CLAIM)   |   |                |                      |                        |            |
|            | Insured Veh.  | YN 9157C                                    | Veh. Inspected | d                    | SMS 8181D              |            |
|            | Policy No.  | DMCVSNA00088702000                          | Coverage (\$)  |                      | 0.00                   |            |
|            | Claim No.   | SNM21D204439/C02/YN9157C/<br>LEWLC          | Excess (\$)    |                      | 0.00                   |            |
|            | Assign From   | JENNY LEW                                   | Assign Date    |                      | 1 <del>2/00/2021</del> | 08.11.2021 |
| : <b>.</b> |   | Vehicle Partic                              | ulars & Condit | ion                  |                        |            |
|            | Make & Model  |   | c.c            |                      | 0                      |            |
|            | Engine No.  | HIDDEN                                      | Year of Reg.   |                      |                        |            |
|            | Chassis No.   |   | Colour         |                      |                        |            |
|            | Odometer  | -   | Steering       |                      |                        |            |
|            | Brakes  |   | Modification   |                      |                        |            |
|            | General   |   |                |                      |                        |            |
|            |   | Condition                                   | ons of Tyres   |                      |                        |            |
|            |   | Size  | Make           |                      | Balance                |            |
|            | R/H Front Tyre  |   |                |                      | mm                     |            |
|            | L/H Front Tyre  |   |                |                      | mm                     |            |
|            | R/H Rear Tyre   |   |                |                      | mm                     |            |
|            | L/H Rear Tyre   |   |                |                      | mm                     |            |
| •          |   | Description                                 | on of Damages  |                      |                        |            |
|            |   |   |                |                      |                        |            |
| j          |   | General                                     | Information    |                      |                        |            |
|            | Accident Date   | 09/08/2021                                  | Inspection Dat | te                   | 13/08/2021             |            |
|            | Survey held at  | A S AUTO SERVICE                            |                |                      |                        |            |
|            |   | NO 1 KAKI BUKIT #01-106<br>SINGAPORE 417883 |                |                      |                        |            |
| ia.        | Remarks   |   |                |                      |                        |            |
|            | A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. |   |                |                      |                        |            |