

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG21011419/AVCN2**Date:** 20/01/2022**REFERENCE**

Insured/Claimant: AMANDA KOH TING TING Policy No: 1900249336
Date of Loss: 02/11/2021 Nature of Claim: OD Claim No: 9461654347SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMW820A**
Make & Model: AUDI A3, 999cc TFSI S TRONIC (LED) (A) Engine No: CHZC31378
Reg. Date: 25/11/2019 (Man. Year: 2019) Chassis No: WAUZZZ8V1KA101933
Colour: Grey Odometer: 17124 km
Engine Capacity: 999 cc
Market Value/New Car Price: S\$102,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55R16 Rear Tyre Size: 205/55R16
Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm
Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,012.12	6,470.40	5,541.72	46.13
Miscellaneous Items	0.00	0.00	0.00	
Labour	10,282.00	2,852.00	7,430.00	72.26
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	22,294.12	9,322.40	12,971.72	58.18
+ GST 7.00/7.00% (S\$)	1,560.59	652.57	908.02	58.18
Nett Amount (S\$)	23,854.71	9,974.97	13,879.74	58.18

INSPECTION

Date of Assignment: 09/11/2021

Date Inspected: 08/11/2021 Inspected At:

Premium Automobiles Pte Ltd (UBI)
55 Ubi Road 1
Singapore 408699

Estimated Period of Repair: 4.0 days

Adjuster: ADRIAN LING**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	1,944.00 FS	*1,555.20 FS
2	1		*REAR BUMPER FIXING PARTS	Not Necessary	193.00 FS	*- FS
3	1		*REAR BUMPER ADAPTER-LH	Not Necessary	38.00 FS	*- FS
4	2		*REAR BUMPER TOP GUIDE SECTION-LH/RH	Not Necessary	32.00 FS	*- FS
5	2		*REAR BUMPER LOCKING MECHANISM	Not Necessary	59.00 FS	*- FS
6	1		*REAR BUMPER SPOILER	Cut	237.00 FS	*189.60 FS
7	1		*REAR LIGHT REFLECTOR-LH	Cracked	41.00 FS	*32.56 FS
8	2		*REAR TAIL LIGHT-INNER/OUTER	Cut	1,754.00 FS	*1,403.20 FS
9	2		*REAR TAIL LIGHT TRIM-LH/RH	Not Necessary	60.00 FS	*- FS
10	1		*REAR BUMPER REINFORCEMENT	Not Necessary	603.00 FS	*- FS
11	2		*REAR BUMPER BRACKET-LH/RH	Not Necessary	56.00 FS	*- FS
12	1		*REAR BUMPER GUIDE SECTION-LH	Not Necessary	67.00 FS	*- FS
13	2		*REAR PARKING AID SENSOR	Damaged	195.12 FS	*195.12 FS
14	1		*REAR LID	Dented	3,404.00 FS	*2,723.20 FS
15	1		*REAR LID ATTACHMENT PARTS	Not Necessary	295.00 FS	*- FS
16	1		*REAR LID GASKET	Necessary	205.00 FS	*164.00 FS
17	1		*ADHESIVE	Necessary	19.00 FS	*14.88 FS
18	1		*AUDI EMBLEM	Necessary	138.00 FS	*110.00 FS
19	1		*A3 EMBLEM	Necessary	99.00 FS	*79.04 FS
20	1		*REAR END PANEL	Not Necessary	360.00 FS	*- FS
21	1		*REAR END PANEL REINFORCEMENT	Not Necessary	733.00 FS	*- FS
22	2		*REAR END PANEL CONNECTING PLATE-LH/RH	Not Necessary	290.00 FS	*- FS
23	1		*REAR NO PLATE	Not Necessary	60.00 FS	*- FS
24	1		*A/SEALANT	Not Necessary	180.00 FS	*- FS
25	1		*C/WAX	Not Necessary	140.00 FS	*- FS
26	1		*METAL FILLER POWDER	Not Necessary	280.00 FS	*- FS
27	1		*STONE CHIP	Not Necessary	180.00 FS	*- FS
28	1		*SUNDRIES	Necessary	350.00 FS	*3.60 FS

F=Franchise part. S=SpcNett.

Total Parts (S\$)	12,012.12	6,470.40
--------------------------	------------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND TRANSFER REAR PARKING AID.CHECK FUNCTION	New	280.00	280.00
2	TO REMOVE AND REINSTALL REAR LIDS CONVENIENCE LOCK SYSTEM AND WIRE HARNESS FOR TAIL LIGHTS	New	280.00	280.00
3	TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR LIGHTS,BATTERY MANAGER,FUSE AND RELAY TRAYS,ELECTRICAL AND AUDIO EQUIPMENT.INSPECT FOR DAMAGE AND RENEW WHERE NECESSARY	New	480.00	0.00
4	TO DISMANTLE AND RENEW REAR BUMPER AND REAR LID.TO CUT OUT AND WELD REAR END PANELLING.TO REPAIR LHS REAR FENDER.RE-ORGANIZE CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED	New	4,550.00	1,000.00
5	TO RESPRAY REAR BUMPER,REAR LID,REAR END PANELLING,LHS REAR FENDER AND SPARE WHEEL HOUSING	New	4,500.00	1,100.00
6	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (\$\$)			10,282.00	2,852.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >