

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21011420/AVY3N2**Date:** 24/05/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNW00067782100

Claimant Vehicle No : SMS359L **Insured Vehicle No :** SJD2103J

Date of Loss: 06/11/2021 Nature of Claim: TP Claim No: SNM21D206385/C02/TANKW

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMS359L**

Make & Model: HONDA FIT, 1.3 (A) Engine No: L13B3942671

Reg. Date: 06/02/2020 (Man. Year: 2019) Chassis No: GK33428178

Colour: Grey Odometer: 14920 km

Engine Capacity: 1317 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/45R16 Rear Tyre Size: 205/45R16

Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm

Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,315.00	5,036.52	3,278.48	39.43
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,130.00	2,080.00	1,050.00	33.55
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	11,445.00	7,116.52	4,328.48	37.82
Approved Total (Overridden) (\$\$)		5,600.00		
(\$\$)	11,445.00	5,600.00	5,845.00	51.07
+ GST 7.00/7.00% (\$\$)	801.15	392.00	409.15	51.07
Nett Amount (\$\$)	12,246.15	5,992.00	6,254.15	51.07

INSPECTION

Date of Assignment: 11/11/2021

Date Inspected: 09/11/2021 Inspected At: N-51 Automotive (HQ)
2 KAKI BUKIT AVE 2 #01-18
Singapore 417921

Estimated Period of Repair: 7.0 days

Adjuster: ADRIAN LING**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 23 May 2022)
Parts:	144	HONDA FIT 1.3 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMS359L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	890.40 FL	*495.00 FL
2	1		*REAR BUMPER CENTER GARNISH	Cracked	139.30 FL	*139.30 FL
3	2		*REAR BUMPER SIDE GARNISH L/R	Cracked	116.60 FL	*116.60 FL
4	2		*REAR BUMPER SIDE RETAINER L/R	Cracked	23.00 FL	*23.00 FL
5	1		*REAR END PANEL	Dented	539.10 FL	*539.10 FL
6	1		*REAR END PANEL ANTENNA SENSOR	Cracked	85.00 FL	*85.00 FL
7	1		*REAR END PANEL BUZZLE SENSOR	Cracked	85.00 FL	*85.00 FL
8	1		*REAR END PANEL INNER TOP GARNISH	Cracked	160.80 FL	*160.80 FL
9	1		*REAR EXHAUST GASKET	Not Necessary	40.00 FL	*- FL
10	2		*REAR EXHAUST RUBBER MOUNTING	Not Necessary	50.00 FL	*- FL
11	2		*REAR FENDER INNER TRIM GARNISH L/R	Cracked	561.40 FL	*561.40 FL
12	1		*REAR FLOOR PANEL TOP BOARD COVER	Damaged	289.80 FL	*289.80 FL
13	1		*REAR SPARE TYRE PANEL	Repair	697.00 FL	*- FL
14	1		*REAR TAILGATE	Distorted	1,080.70 FL	*955.00 FL
15	1		*REAR TAILGATE FIT EMBLEM	Necessary	48.20 FL	*48.20 FL
16	1		*REAR TAILGATE INNER PULL HANDLE	Deformed	18.20 FL	*18.20 FL
17	1		*REAR TAILGATE LOCK STRIKER	Not Necessary	27.50 FL	*- FL
18	1		*REAR TAILGATE MECHANISM LOCK	Damaged	88.90 FL	*88.90 FL
19	1		*REAR TAILGATE WEATHER STRIP	Cut	92.30 FL	*92.30 FL
20	1		*REAR TAILGATE WINDSCREEN MOULDING	Necessary	95.60 FL	*95.60 FL
21	2		*REAR TAILLAMP L/R	Cracked	591.50 FL	*591.50 FL
22	1		*REAR TOOL SPONGE TRAY	Torn	220.00 FL	*220.00 FL
23	1		*SET REAR BUMPER CLIPS	Necessary	50.00 FS	*50.00 FS
24	1		*REAR BUMPER LOWER SPOILER	Cracked	800.00 FS	*500.00 FS
25	1		*SET REAR BUMPER REVERSE SENSOR	Damaged	250.00 FS	*200.00 FS
26	1		*REAR BUMPER STICKER	Necessary	150.00 FS	*40.00 FS
27	1		*SET REAR END PANEL INNER TOP GARNISH CLIPS	Necessary	20.00 FS	*10.00 FS
28	1		*REAR EXHAUST SILENCER BOX (LOCAL REPAIR)	Bent	1,600.00 FS	*200.00 FS
29	2		*SET REAR FENDER INNER TRIM GARNISH CLIPS L/R	Necessary	60.00 FS	*60.00 FS
30	1		*REAR NUMBER PLATE	Necessary	25.00 FS	*25.00 FS
31	1		*REAR NUMBER PLATE HOLDER	Deformed	50.00 FS	*30.00 FS
32	1		*REAR SPARE TYRE PANEL INSULATOR MAT	Not Necessary	300.00 FS	*- FS
33	1		*SET REAR TAILGATE INNER TRIM GARNISH CLIPS	Necessary	50.00 FS	*50.00 FS
34	1		*REAR TAILGATE WINDSCREEN SEALANT	Necessary	80.00 FS	*60.00 FS
35	2		*REAR TAILGATE INNER RUBBER SIDE GUIDE STOPPER L/R	Necessary	21.00 FL	*21.00 FL
36	1		*REAR TAILGATE INNER TRIM	Cracked	138.70 FL	*138.70 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	9,535.00	5,989.40
- List Item Discount on L Items 20.00/20.00% (\$\$)	1,220.00	952.88
Total Parts (\$\$)	8,315.00	5,036.52

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE,REINSTALL ELECTRICAL WIRING HARNESS,CHECK LIGHTING AND REWIRE FOR PARKING SENSOR	New	80.00	80.00
2	TO REMOVE,REINSTALL TAILGATE WINDSCREEN	New	150.00	120.00
3	TO REMOVE,REINSTALL ROOF TOP TRIM UPHOLSTERY,CUSHION SEAT,TRIM GARNISH,TRIM LINER CARPET (TO FR)	New	100.00	60.00
4	TO RE-SPRAY PAINTING ON THE CHANGE BODYPARTS,REPAIR PORTION,AND WHERE CONSISTENT TO THE ACCIDENT	New	1,300.00	800.00
5	TO REMOVE AND CHANGE EXHAUST SILENCER BOX WITH PIPE,RE-ALIGN WHERE NECESSARY CONSISTENT TO THE ACCIDENT	New	100.00	80.00
6	TO PROVIDE LABOUR,WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS,REPAIR,RE-CONSTRUCT AND RE-ALIGN BODY STRUCTURE,BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT	New	1,200.00	800.00
7	TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLACED PANEL	New	120.00	60.00
8	TO REMOVE,REINSTALL TAILGATE MECHANISM AND CHECK FOR FUNCTION	New	80.00	80.00
Gross Labour Cost (\$\$)			3,130.00	2,080.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >