

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG21011423/AVCE2

Date: 18/05/2022

REFERENCE

Insured/Claimant: MARGARET TEOH WEI LING
Date of Loss: 30/10/2021

Policy No:
Nature of Claim: OD Claim No: 1565884033SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLN2389A**
Make & Model: AUDI A4, 1.4 TFSI S TRONIC (A) Engine No: CVN032589
Reg. Date: 26/04/2017 (Man. Year: 2017) Chassis No: WAUZZZF45HA122027
Colour: White Odometer: 95040 km
Engine Capacity: 1395 cc
Market Value/New Car Price: S\$88,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/60 R16 Rear Tyre Size: 205/60 R16
Front Left Side: Pirelli 6 mm Rear Left Side: Pirelli 6 mm
Front Right Side: Pirelli 6 mm Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	19,604.00	11,448.80	8,155.20	41.60
Miscellaneous Items	0.00	0.00	0.00	
Labour	17,022.00	13,712.00	3,310.00	19.45
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	36,626.00	25,160.80	11,465.20	31.30
- Excess (S\$)	300.00	300.00	0.00	0.00
(S\$)	36,326.00	24,860.80	11,465.20	31.56
+ GST 7.00/7.00% (S\$)	2,542.82	1,740.26	802.56	31.56
Nett Amount (S\$)	38,868.82	26,601.06	12,267.76	31.56

INSPECTION

Date of Assignment: 09/11/2021

Date Inspected: 02/11/2021 Inspected At:

24 Benoi Sector

Repairer: Premium Automobiles Pte Ltd

Estimated Period of Repair: 15.0 days

Adjuster: ADRIAN LING

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SECTIONAL PART - SIDE MEMBER LH	Dented	2,174.00 FS	*1,739.20 FS
2	1		*SILL TRIM STRIP - LH	Necessary	120.00 FS	*96.00 FS
3	1		*FRONT DOOR - LH	Distorted	3,192.00 FS	*2,553.60 FS
4	1		*FRONT DOOR OUTER SEAL - LH	Necessary	205.00 FS	*164.00 FS
5	1		*BONDING AGENT	Not Necessary	49.00 FS	*- FS
6	1		*CLEANING SOLUTION	Not Necessary	68.00 FS	*- FS
7	1		*APPLICATOR	Not Necessary	8.00 FS	*- FS
8	1		*FRONT DOOR ATTACHMENT PARTS - LH (NPA)	Not Necessary	0.00 FS	*- FS
9	1		*FRONT DOOR CATCH - LH	Not Necessary	105.00 FS	*- FS
10	1		*REAR DOOR - LH	Distorted	3,192.00 FS	*2,553.60 FS
11	1		*REAR DOOR OUTER SEAL - LH	Necessary	205.00 FS	*164.00 FS
12	1		*BONDING AGENT	Not Necessary	49.00 FS	*- FS
13	1		*CLEANING SOLUTION	Not Necessary	68.00 FS	*- FS
14	1		*APPLICATOR	Not Necessary	8.00 FS	*- FS
15	1		*SEALING STRIP	Not Necessary	17.00 FS	*- FS
16	1		*REAR DOOR ATTACHMENT PART - LH	Not Necessary	860.00 FS	*- FS
17	1		*REAR DOOR CATCH - LH	Damaged	120.00 FS	*96.00 FS
18	1		*REAR DOOR HINGE HALF - LH UPPER PART	Bent	44.00 FS	*34.48 FS
19	1		*REAR DOOR HINGE HALF - LH UPPER PART	Bent	46.00 FS	*35.84 FS
20	1		*REAR DOOR HINGE HALF - LH LOWER PART	Bent	46.00 FS	*36.40 FS
21	1		*REAR DOOR HINGE HALF - LH LOWER PART	Bent	46.00 FS	*36.40 FS
22	1		*REAR DOOR SEAL, INNER - LH	Cut	222.00 FS	*177.60 FS
23	1		*REAR DOOR TRIM PLATE FOR DOOR PLATE	Cracked	88.00 FS	*69.92 FS
24	1		*REAR DOOR HANDLE HOUSING - LH	Damaged	8.00 FS	*5.92 FS
25	1		*REAR DOOR MOUNTING BAR - LH	Damaged	164.00 FS	*130.80 FS
26	1		*REAR WINDOW REGULATOR - LH	Damaged	282.00 FS	*225.60 FS
27	1		*REAR WINDOW REGULATOR MOTOR - LH	Damaged	338.00 FS	*270.40 FS
28	1		*REAR DOOR CONTROL UNIT - LH	Not Necessary	751.00 FS	*- FS
29	1		*REAR DOOR PANEL - LH	Not Necessary	1,792.00 FS	*- FS
30	1		*REAR DOOR WIRING HARNESS - LH	Not Necessary	297.00 FS	*- FS
31	1		*REAR DOOR WIRING SET - LH	Snapped	374.00 FS	*298.80 FS
32	1		*AIRBAG STICKER	Necessary	24.00 FS	*19.04 FS
33	1		*FRONT WINDOW SLOT SEAL - LH	Not Necessary	307.00 FS	*- FS
34	1		*REAR WINDOW SLOT SEAL - LH	Damaged	366.00 FS	*292.40 FS
35	1		*TRIM STRIP FOR WINDOW - LH	Not Necessary	257.00 FS	*- FS
36	1		*TRIM STRIP FOR WINDOW - LH	Not Necessary	237.00 FS	*- FS
37	1		*B-PILLAR TRIM, GLOSSY BLACK - LH	Not Necessary	228.00 FS	*- FS
38	1		*B-PILLAR TRIM, GLOSSY BLACK - LH	Necessary	147.00 FS	*119.20 FS
39	1		*C-PILLAR TRIM, GLOSSY BLACK - LH	Necessary	142.00 FS	*113.60 FS
40	1		*ARCYLIX SEALANT	Necessary	180.00 FS	*180.00 FS
41	1		*CAVITY WAX	Necessary	140.00 FS	*140.00 FS
42	1		*STONE CHIP	Necessary	180.00 FS	*180.00 FS
43	1		*METAL FILLER POWDER	Necessary	280.00 FS	*280.00 FS
44	1		*SUNDRIES	Necessary	450.00 FS	*53.44 FS
45	1		*BASS LOUDSPEAKER-LH REAR (Supplementary)	Cracked	141.00 FS	*112.80 FS
46	1		*REAR DOOR WIRING HARNESS CONNECTOR (Supplementary)	Damaged	17.00 FS	*13.60 FS
47	1		*REAR DOOR LOCK-LH (Supplementary)	Damaged	661.00 FS	*528.40 FS
48	1		*REAR DOOR UNDERLAY-LH REAR (Supplementary)	Deformed	4.00 FS	*2.88 FS
49	1		*REAR DOOR UNDERLAY-LH FRONT (Supplementary)	Deformed	4.00 FS	*2.88 FS
50	1		*REAR DOOR HANDLE, EXTERIOR-LH (Supplementary)	Damaged	44.00 FS	*37.28 FS

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
51	1		*REAR DOOR HANDLE SENSOR-LH (Supplementary)	Damaged	228.00 FS	*182.40 FS
52	1		*REAR DOOR HANDLE PERIPHERAL LIGHT-LH (Supplementary)	Cracked	72.00 FS	*57.28 FS
53	1		*REAR DOOR HANDLE TRANSPARENT COVER LH (Supplementary)	Necessary	6.00 FS	*4.64 FS
54	1		*B-PILLAR PANEL-LH INNER (Supplementary)	Dented	551.00 FS	*440.40 FS

F=Franchise part. S=SpcNett.

Total Parts (S\$)	19,604.00	11,448.80
--------------------------	------------------	------------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND TRANSFER LHS FRONT DOORS AND LHS REAR DOORS MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES	New	700.00	560.00
2	TO CARRY OUT FIRST MEASUREMENT TEST ON CAR-O-LINER	New	800.00	800.00
3	TO PUT ON THE VEHICLE ON CAR-O-LINER TO FACILITATE THE REPAIR	New	2,400.00	2,400.00
4	TO REMOVE AND REINSTALL LHS FRONT SEAT ASSY, REAR SEATS ASSY, ABCD PILLAR TRIMS, SILL TRIMS, FLOOR CARPETS, ELECTRONIC COMPONENTS AND FUSE TRAYS. DISENGAGE LHS SEAT BELT AND HEAD AIRBAG	New	2,400.00	2,400.00
5	TO DISMANTLE AND RENEW LHS FRONT DOOR AND LHS REAR DOOR. TO CUT OUT AND WELD LHS B-PILLAR AND LHS SILL PANEL. TO REPAIR LHS REAR FENDER. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	5,250.00	4,250.00
6	TO RESPRAY LHS FRONT DOOR, LHS REAR DOOR, DOOR HANDLES, DOOR ENTRANCES, LHS REAR FENDER, LHS B-PILLAR AND LHS SILL PANEL	New	5,000.00	2,830.00
7	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
8	TO RECTIFY AND RENEW DAMAGE WIRE, CHECK ELECTRIC SYSTEM AND FUNCTION (Supplementary)	New	280.00	280.00
Gross Labour Cost (S\$)			17,022.00	13,712.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >