Adjuster Report 11/22/21, 8:57 AM

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG21011430/R1VF3Q2

22/11/2021 Date:

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2070174024 **Claimant Vehicle**

SLU3978G Insured Vehicle No: SMW8609S No:

07/11/2021 Nature of Claim: TP Claim No: 0966300751SG Date of Loss:

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLU3978G**

Make & Model: KIA CERATO, 1.6 (A) Engine No: G4FGHH684486 Reg. Date: 30/11/2017 (Man. Year: 2017) Chassis No: KNAFJ411MJ5749587

Colour: Odometer: 212680 km Blue

Engine Capacity: 1591 cc Market Value/New Car Price: N/A

Market Value/New Car Price Sum Insured (S\$):

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): **Engine Modification:** No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15 Front Left Side: Rear Left Side: Kumho 6 mm Kumho 6 mm Front Right Side: Rear Right Side: Kumho 6 mm Kumho 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

09/11/2021 Date of Assignment:

160 SIN MING DRIVE #06-10 AUTOCITY Date Inspected: 10/11/2021 Inspected At:

Repairer:Lian Heng Painter Company (HQ)

Estimated Period of Repair: 6.0 days

Adjuster: MOHD RASUL Manager: **VERON CHEN**

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

MARKET VALUE:\$55,000.00

REPAIR DETAILS

Recommended Parts

No.	Qty Part No.	Particulars	Condition	Repairer's	Amount
1	1	*FRT LH DOOR	Buckled	0.00 F	*- F
2	1	*FRT LH DOOR GLASS REGULATOR	Cracked	0.00 F	*- F
3	1	*FRT LH DOOR OUTER HANDLE	Cracked	0.00 F	*-F
4	1	*FRT LH DOOR LOCK W/KEY	Bent	0.00 F	*- F
5	1	*CENTRE PILLAR LH	Repair	0.00 F	*- F
6	1	*ROCKER PANEL LH	Repair	0.00 F	*-F
7	1	*FRT LH FENDER	Repair	0.00 F	*- F
8	1	*REAR LH DOOR	Repair	0.00 F	*- F
F=Frai	nchise part.				
			Total Parts (S\$)	0.00	0.00

Report was unsubmitted during this print-out.

11/22/21, 8:57 AM Adjuster Report

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >