

No. 1 Kaki Bukit Ave 6 #01-53 AutoBay @ Kaki Bukit Singapore 417883 Tel: 81818802 Fax: 67471017 Registration No: 201000268D

Report Reference: TP/

09-21004/DY / 2021

Date of Report

: 30 Sep 2021

Ultimate Display System Pte Ltd c/o Blk 9002 Tampines Street 93

#01-34

Singapore 528836

THIRD PARTY SURVEY **ACCIDENT HAPPENED ON**

18 Sep 2021

As per your instruction dated 23 Sep 2021 carried out a physical inspection on the said vehicle our report and findings as follows:

with regard to the above matter. We have GBD 4061 C . We enclosed herewith

1. VEHICLE PARTICULARS

Registration No : GBD 4061 C

Model

: Nissan Cabstar

Year / Capacity : 2014/2953

Chassis No

: JN1SC2F24Z0856564

Engine No

: ZD30342354K

Mileage

: 319314

Colour

: Silver

2. TYRES CONDITION

			<u>Size</u>	<u>Made</u>	<u>Balance</u>		<u>Rim</u>
FRONT	O/S	:	195 R15	Yokohama	8.00	mm	Normal
REAR	O/S	:	165 R13	Yokohama	8.00/8.00	mm	Normal
FRONT	N/S	:	195 R15	Yokohama	8.00	mm	Normal
REAR	N/S	• •	165 R13	Yokohama	8.00/8.00	mm	Normal



No. 1 Kaki Bukit Ave 6 #01-53 AutoBay @ Kaki Bukit Singapore 417883 Tel: 81818802 Fax: 67471017 Registration No: 201000268D

3. DESCRIPTION OF DAMAGES

At the time of inspection, we noted that the vehicle has sustained an impact damages on the front n/s portion(s). For more detail of the damages, please see photograph attached.

4. Workshop Address : Yeow Koon Motor Spray Painting

Blk 9002 Tampines Street 93

#01-34

Singapore 528836

5. Estimated normal period of repair

working days to complete.

6. Enclosed number of photograph

64 copies.

6

- 7. In accordance to your instruction, we have Not Authorised repair to the vehicle and the survey was done on a "Without Prejudice" basis. We hope that this report will be of assistance to you in dealing with the matter.
- 8. Should you discover any discrepancy in the report, please kindly notify us within 2 weeks, or the report will be treated as correct.

The rates and assessment of damages as stated in this report is to be used solely for legal proceedings in relation to the surveyed vehicle and the accident in which the surveyed vehicle was involved in. The rates and assessment of damages must not be used in any circumstances for comparison with other vehicles and/or other accidents in other legal proceedings.

Vehicle No:

GBD 4061 C

Report No:

TP/ 09-21004/DY / 2021

SPARE PARTS

Qty	Parts Description		Condition	Workshop's Estimation		r Revised timation
	Nett Items					
1	Front headlamp		Damage	\$	518.50	\$ 518.50
1	Front headlamp lower garnish		Damage	\$	81.30	\$ 81.30
1	Front corner panel		Damage	\$	436.30	\$ 436.30 303.50
1	Front grille		Intact	\$	578.10	\$
1	Front bumper		Damage	\$	675.40	\$ 675.40
1	Front door		Repair	\$	1474.10	\$
1	Front door rubber		Intact	\$	144.60	\$
1	Front door mirror		Damage	\$	183.20	\$ 183.20
1	Front door mirror stay		Damage	\$	207.90	\$ 207.90 150
1	Front door mirror (Round)		Damage	\$	87.10	\$ 87.10
1	Front door pillar		Repair	\$	1842.40	\$
				\$	6228.90	\$ 2189.70 1999
		Discount	10.0%	\$_	622.89	\$ 218.97 1799.10
				\$	5606.01	\$ 1970.73
	Special Nett Items					
1	Front door lettering sticker		Necessary	\$	45.00	\$ 45.00
				\$	45.00	\$ 45.00
						45

Vehicle No:

GBD 4061 C

Report No:

TP/ 09-21004/DY / 2021


LABOUR COST


S/No	Job Descriptions	Workshop's Estimation		r Revised timation
	Spare Parts Total c/f	\$	5651.01	\$ 2015.73
1	To remove and refit damage parts, test for proper functioning and focus of headlamps.	\$	40.00	\$ 30.00
2	To remove and refit the door lock mechanism, regulator gear, window glass, handle, inner board, hinges, channel to facilitate the repairs.	\$	180.00	\$ 80.00 XNN
3	To remove and replace the above damaged parts, straighten, knock out, realign and repair including cut and wield body panels. To re-adjust to the original position using power tools.	\$	1000.00	\$ 600 880.00
4	To spray paint on the replaced and repaired parts, prepare spray such as masking tape the unaffected areas with paper, cleaning and sanding of surfaces, final polishing and waxing are also available.	\$	900.00	\$ 600 660.00
5	To apply undercoating on the repaired and replaced panels for rust protection.	\$	120.00	\$ 30 60.00
				1260
	Total	\$	7891.01	\$ 3725.73
	Recommended PART BY PART Repair Amount of:	\$	3725.73	\$3104.10 5 DAYS


SDLS: THREE THOUSAND SEVEN HUNDRED TWENTY FIVE AND CENTS SEVENTY THREE ONLY

Qualified Appraiser





























CHASSIS NO: JN1SC2F24Z0856564

11.W - : 1780 KGS 11.W : 3500 KGS 12. P. CAP : F: 1 DRIVER, 2 OTHERS 13. R: 00 14. R: 00 15. R: 155 x 13R 8PLY (D)

SP