

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC4/GRB21011432/DEA3Q2**Date:** 17/05/2022REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D21MFL0000447
<b>Claimant Vehicle No :</b>	FBP8307E	<b>Insured Vehicle No :</b>	SMQ2442B
Date of Loss:	06/11/2021	Nature of Claim:	TP
		Claim No:	MFL2021D0004890

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>FBP8307E</b>		
Make & Model:	YAMAHA AEROX GDR155A, 155cc CVT ABS	Engine No:	G3J8E0104812
Reg. Date:	18/06/2019 (Man. Year: 2019)	Chassis No:	MH3SG4640KJ055919
Colour:	Black/White	Odometer:	45120 km
Engine Capacity:	155 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	120/70 R14	Rear Tyre Size:	140/60 R14
Front Left Side:	Michelin 2 mm	Rear Left Side:	Michelin 2 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	792.00	198.00	594.00	75.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	150.00	60.00	90.00	60.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>942.00</b>	<b>258.00</b>	<b>684.00</b>	<b>72.61</b>
<b>+ Loss of Use (1.0 x S\$25.00/day) (S\$)</b>		25.00		
	<b>Nett Liability (S\$)</b>	<b>283.00</b>		

INSPECTION

Date of Assignment:	09/11/2021	Sg 98 Motor Pte Ltd (HQ)
Date Inspected:	10/11/2021 Inspected At:	BLK 4001 ANG MO KIO INDUSTRIAL PARK 1
		#01-21
		Singapore 569622
Estimated Period of Repair:	1.0 days	

**Adjuster:** BRYAN TANI**Manager:** Asher Sng Rong Yi

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 17 May 2022)	
Parts:	N/A	YAMAHA AEROX GDR155A 155cc CVT ABS (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FBP8307E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR MUDGUARD	Distorted / Deformed	220.00 FL	*220.00 FL
2	1		*NUMBER PLATE HOLDER	Serviceable	80.00 FL	*- FL
3	1		*EXHAUST PIPE	Repair	580.00 FL	*- FL
						F=Franchise part. L=ListItemDisc.
					Sub Total (S\$)	880.00 220.00
					- List Item Discount on L Items 10.00/10.00% (S\$)	88.00 22.00
					Total Parts (S\$)	792.00 198.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	LABOUR CHARGE	New	150.00	60.00
<b>Gross Labour Cost (\$\$)</b>			<b>150.00</b>	<b>60.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >