

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG21011433/UGS3Q2**Date:** 01/03/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900110879
Claimant Vehicle No :	GBE7414T	Insured Vehicle No :	SMM4153T
Date of Loss:	06/11/2021	Nature of Claim:	TP
		Claim No:	3716931242SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBE7414T		
Make & Model:	TOYOTA HIACE, 3.0 D TURBO 5 DR (M)	Engine No:	1KD2592843
Reg. Date:	15/03/2016 (Man. Year: 2016)	Chassis No:	JTFHT02P500190566
Colour:	Silver	Odometer:	84269 km
Engine Capacity:	2982 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195 R15	Rear Tyre Size:	195 R15
Front Left Side:	ONYX 6 mm	Rear Left Side:	ONYX 6 mm
Front Right Side:	ONYX 6 mm	Rear Right Side:	ONYX 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,640.00	800.00	840.00	51.22
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	1,640.00	800.00	840.00	51.22
+ GST 7.00/7.00% (S\$)	114.80	56.00	58.80	51.22
Nett Amount (S\$)	1,754.80	856.00	898.80	51.22
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment:	18/11/2021		
Date Inspected:	18/11/2021	Inspected At:	Jin Auto Services Pte Ltd (Defu) Blk 14 Defu Lane 10, #01-410/412 Singapore 539195
Estimated Period of Repair:	2.0 days		

Adjuster: MARCUS CHUA**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	SPRAY PAINTING	New	880.00	600.00
2	LABOUR CHARGE	New	380.00	200.00
3	ARTWORK	New	380.00	0.00
Gross Labour Cost (\$)			1,640.00	800.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >