



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLE 3296A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT BUMPER (N) (CONSISTENT)	DISTORTED	495.80	459.80
1	FRONT BUMPER TOW COVER (N) (CONSISTENT)	TORN	12.60	12.60
1	FRONT BUMPER FOG LAMP RH (N) (CONSISTENT)	CRACKED	277.60	277.60
1	FRONT BUMPER FOG LAMP COVER (N) (CONSISTENT)	DISTORTED	82.10	82.10
1	FRONT BUMPER REINFORCEMENT (N) (CONSISTENT)	DENTED	377.50	265.60
2	FRONT BUMPER SIDE RETAINER RH/LH @\$45.20	O/S BENT	90.40	25.00
1	FRONT BONNET (N) (CONSISTENT)	TO REPAIR SEE LABOUR	579.80	-
1	FRONT BONNET LOCK (N) (CONSISTENT)	NOT NECESSARY	120.30	-
1	FRONT FENDER RH (N) (CONSISTENT)	BENT / BUCKLED	453.80	453.80
1	FRONT FENDER INNER SHIELD (N) (CONSISTENT)	NOT NECESSARY	126.80	-
15	FRONT FENDER INNER SHIELD CLIPS @\$5.50 (N) (CONSISTENT)	NOT NECESSARY	82.50	-
1	FRONT GRILLE BASE (N) (CONSISTENT)	CRACKED	186.90	186.90
1	FRONT GRILLE CHROME MOULDING (N) (CONSISTENT)	SCRATCHED	199.60	181.86
1	FRONT GRILLE LOGO (N) (CONSISTENT)	NECESSARY	58.80	58.80
1	FRONT HEADLAMP ASSY RH (N) (CONSISTENT)	CRACKED	585.90	585.90
1	FRONT HEADLAMP LOWER BRACKET (N) (CONSISTENT)	CRACKED	89.60	89.60
1	FRONT SUPPORT PANEL (N) (CONSISTENT)	TO REPAIR SEE LABOUR	479.30	-
1	AIR CON CONDENSER (N) (CONSISTENT)	NOT NECESSARY	670.90	-
1	WIPER TANK (N) (CONSISTENT)	DEFORMED	182.60	182.60
	LESS 20% DISCOUNT		-1,030.56	-572.43
			4,122.24	2,289.73
<u>SPECIAL NETT ITEMS</u>				
1	SET FRONT BUMPER CLIPS (SN) (CONSISTENT)	NECESSARY	45.00	30.00
1	SET FRONT NUMBER PLATE WITH HOLDER (N) (CONSISTENT)	SCRATCHED	60.00	40.00
			105.00	70.00
<u>LABOUR</u>				
	TO CHECK FRONT ELECTRICAL WIRING.		50.00	20.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO TUFF KOTE.		60.00	30.00
	TO PUTTY, SPRAY PAINT & POLISH AFFECTED PARTS.		1,080.00	780.00
	PANEL BEATING, CUT, WELD, REMOVE & REPLACING ABOVE PARTS. INCLUSIVE OF THE REPAIR OF FRONT BONNET AND FRONT SUPPORT PANEL.		1,050.00	580.00
			2,240.00	1,410.00
GRAND TOTAL			6,467.24	3,769.73
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				3,000.00

Report Ref No. CC4/ASM21011436/Ups3q2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.