

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG21011440/APS3Q2**Date:** 14/03/2022**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800144315
Claimant Vehicle No :	SJQ3676Y	Insured Vehicle No :	SMF9839C
Date of Loss:	05/11/2021	Nature of Claim:	TP
		Claim No:	0864355164SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJQ3676Y	Engine No:	CAXF84047
Make & Model:	VOLKSWAGEN JETTA, 1.4 (A)	Chassis No:	WVWZZZ16ZGM020611
Reg. Date:	19/02/2016 (Man. Year: 2015)	Odometer:	130580 km
Colour:	White		
Engine Capacity:	1390 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,688.00	2,327.00	4,361.00	65.21
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,560.00	480.00	2,080.00	81.25
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,248.00	2,807.00	6,441.00	69.65
Approved Total (Overridden) (S\$)		2,200.00		
Nett Amount (S\$)	9,248.00	2,200.00	7,048.00	76.21
+ Car Rental (3.0 x S\$100.00/day) (S\$)		300.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		2,507.45		
Global Sum Settlement (S\$)		2,500.00		

INSPECTION

Date of Assignment:	09/11/2021	Sin Yu Sin Workshop (HQ)
Date Inspected:	09/11/2021 Inspected At:	1 Kaki Bukit Ave 6 #01-52 (Auto Bay @ Kaki Bukit)
Estimated Period of Repair:	3.0 days	Singapore 417883

Adjuster: ADRIAN LING**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT LID	Repair	1,903.00 FL	*- FL
2	1		*REAR BOOT LID JETTA EMBLEM	Not Necessary	78.00 FL	*- FL
3	1		*REAR BOOT LID LOGO EMBLEM	Not Necessary	116.00 FL	*- FL
4	1		*REAR BOOT LID TSI EMBLEM	Not Necessary	65.00 FL	*- FL
5	1		*REAR BUMPER	Deformed	1,322.00 FL	*1,147.00 FL
6	1		*REAR BUMPER LOWER GARNISH	Cut	511.00 FL	*511.00 FL
7	1		*REAR BUMPER SIDE REFLECTOR LH	Not Necessary	116.00 FL	*- FL
8	2		*REAR BUMPER SIDE RETAINER L/R	Not Necessary	193.00 FL	*- FL
9	1		*REAR BUMPER REINFORCEMENT BEAM	Dented	514.00 FL	*514.00 FL
10	1		*REAR BUMPER CENTRE BRACKET	Cracked	158.00 FL	*158.00 FL
11	1		*REAR END PANEL	Not Necessary	890.00 FL	*- FL
12	1		*REAR END PANEL GARNISH	Not Necessary	205.00 FL	*- FL
13	1		*REAR EXHAUST SILENCER BOX	Not Necessary	849.00 FL	*- FL
14	1		*REAR BUMPER CLIP	Necessary	30.00 FS	*30.00 FS
15	1		*REAR BUMPER REVERSE SENSOR	Damaged	350.00 FS	*200.00 FS
16	1		*REAR END PANEL SEALANT	Not Necessary	50.00 FS	*- FS
17	1		*REAR END PANEL GARNISH CLIP	Not Necessary	30.00 FS	*- FS
					Sub Total (\$\$)	7,380.00 2,560.00
					- List Item Discount on L Items 10.00/10.00% (\$\$)	692.00 233.00
					Total Parts (\$\$)	6,688.00 2,327.00

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING AND RECTIFY ELECTRICAL FAULTS WHERE NECESSARY	New	60.00	30.00
2	TO REMOVE AND REPLACE AND REINSTALL REAR REVERSE SENSOR	New	120.00	50.00
3	TO REMOVE AND REINSTALL REAR INTERIOR TRIMS ,GARNISHES ,SEATS ,ETC FOR NECESSARY REPAIRS	New	160.00	0.00
4	TO REMOVE AND REINSTALL REAR EXHAUST	New	120.00	-
5	TO RUSTPROOF AFFECTED AREAS	New	100.00	0.00
6	TO SPRAY PAINTING ON AFFECTED AREA	New	1,000.00	200.00
7	TO STRAIGHTEN REPAIR ,REALIGN ON FRONT AFFECTED AREA AND REPLACE DAMAGED PARTS	New	1,000.00	200.00
Gross Labour Cost (\$\$)			2,560.00	480.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >