

PRS

ASSIGNMENT

From:

Date:

Estimated Cost:

OD ☒ TP ☒ N/S / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s GARAGE 13

of

Insured:

Policy No.


Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: \$27k

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 8 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: YN5618R

Yr Regn: 31 Jul/2014

Type: M.Car / M.Cycle / Bus / Van ☒ Lorry ☒ Taxi / Prime Mover /

Truck / Trailer or

Make: MITSUBISHI CANTER FEB21ER4SDEB:c 2998

Colour: White

A/C: Insured / Std / NI / NA

Sp. Reading: 387270

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: FEB21EA00533

Gen. Cond: ☒ Good ☐ Fair / Poor / BurntSteering: ☒ Inorder ☐ Jammed / Leaked / Burnt orBrake: ☒ Inorder ☐ Jammed / Leaked / Burnt orModi: ☒ Nil ☐ Rim / STD A/Rim or

Tyre Size: F: 195/85R15 YOKO

R: 195/85R15 BS

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 6 mm

R/Bal. 5/5 mm

L/Bal. 6 mm

L/Bal. 5/5 mm

D.O.A.

D.O.I. 09-11-2021

Survey held at

W/S

4PM

Des. of Damages: ☒ Frt ☒ Rea ☐ O/S ☐ N/S ☐ U/C ☐ Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

\$8000 - \$9000

Total Rebate Amount: \$5,300

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech. Insp (\$☐ : A/Weekend (\$

3 + RS. SI

Photos

Other:

TOTAL

Report Filed:

Long Cond / MPB: