

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21011445/UVY3N2**Date:** 22/11/2021**REFERENCE**Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMCVSNW00040282100

**Claimant Vehicle
No :** Q69M**Insured
Vehicle No :** YN4867U

Date of Loss: 31/10/2021

Nature of Claim: TP

Claim
No: SNM21D206422/C02/LEWLC**DESCRIPTION & IDENTIFICATION OF VEHICLE**Reg No: **Q69M**

Make & Model: TOYOTA VELLFIRE, 2.4 DBA-ANH20W (A)

Engine No: 2ARH898446

Reg. Date: 12/12/2017 (Man. Year: 2017)

Chassis No: AGH300124185

Colour: Black

Odometer: 52004 km

Engine Capacity: 2493 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	255/35R19	Rear Tyre Size:	255/35R19
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	31,621.65	7,516.10	24,105.55	76.23
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,130.00	1,260.00	2,870.00	69.49
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	35,751.65	8,776.10	26,975.55	75.45
Approved Total (Overridden) (\$\$)		7,000.00		
Nett Amount (\$\$)	35,751.65	7,000.00	28,751.65	80.42

INSPECTION

Date of Assignment: 10/11/2021

Date Inspected: 10/11/2021 Inspected At:

 15 KAKI BUKIT ROAD 4
 #01-05/53 BARTLEY BIZ CENTRE
 REPAIRER: ASIA MOTORSPORTS SOLUTION
 PTE LTD

Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 22 Nov 2021)

Parts: M1-MPV TOYOTA VELLFIRE 2.4 DBA-ANH20W (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for Q69M)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*FRONT BUMPER ASSY	Deep Cut/Torn	4,901.20 FL	*1,255.10 FL
2	1	*FRONT BUMPER LOWER GRILLE COMPLETE ASSY	Not Necessary	1,889.60 FL	*- FL
3	1	*FRONT BUMPER INNER SUPPORT	No such part	284.10 FL	*- FL
4	1	*FRONT BUMPER RIGHT OUTER CHROME GARNISH	Cut/Torn	1,609.10 FL	*1,609.10 FL
5	1	*FRONT BUMPER RIGHT FOG LAMP	Cracked	551.10 FL	*516.10 FL
6	1	*FRONT BUMPER RIGHT FOG LAMP OUTER GARNISH	Not Necessary	660.50 FL	*- FL
7	1	*FRONT BUMPER RIGHT BRACKET	Not Necessary	128.10 FL	*- FL
8	1	*FRONT BUMPER RIGHT RETAINER	Cracked	155.50 FL	*135.20 FL
9	1	*FRONT RIGHT LED LAMP	Not Necessary	652.50 FL	*- FL
10	1	*FRONT RIGHT LED LAMP GRILLE GARNISH	Not Necessary	880.80 FL	*- FL
11	1	*FRONT BONNET ASSY	Not Necessary	2,610.50 FL	*- FL
12	1	*FRONT BONNET CHROME MOULDING	Not Necessary	359.40 FL	*- FL
13	1	*FRONT GRILLE COMPLETE ASSY	Not Necessary	1,655.50 FL	*- FL
14	1	*FRONT GRILLE EMBLEM	Not Necessary	250.50 FL	*- FL
15	1	*FRONT RIGHT HEADLAMP WITH MODULE COMPLETE ASSY	Cracked	6,805.20 FL	*4,100.10 FL
16	1	*FRONT RIGHT HEADLAMP OUTER GARNISH	Cut	445.10 FL	*117.70 FL
17	1	*FRONT RIGHT HEADLAMP UPPER LID	Cracked	185.50 FL	*150.00 FL
18	1	*FRONT RIGHT HEADLAMP LOWER LID	Cracked	175.80 FL	*150.00 FL
19	1	*FRONT RIGHT FENDER	Dented/Bent	2,255.10 FL	*1,276.00 FL
20	1	*FRONT RIGHT FENDER INNER COWLING	Torn	380.20 FL	*285.50 FL
21	1	*FRONT RIGHT DOOR ASSY	Repair	3,680.10 FL	*- FL
22	1	*FRONT RIGHT DOOR OUTER HANDLE	Not Necessary	85.80 FL	*- FL
23	1	*FRONT RIGHT WING MIRROR COMPLETE ASSY	Not Necessary	1,885.60 FL	*- FL
24	1	*FRONT RIGHT QUARTER GLASS MOULDING	Not Necessary	288.10 FL	*- FL
25	1	*FRONT RIGHT SUSPENSION ASSY	Not Necessary	3,683.90 FL	*- FL
26	1	*FRONT RIGHT LOWER ARM	Not Necessary	702.10 FL	*- FL
27	1	*FRONT RIGHT KNUCKLE ARM	Not Necessary	855.50 FL	*- FL
28	1	*FRONT RIGHT WHEEL HUB BEARING	Not Necessary	345.80 FL	*- FL
29	10	*FRONT BUMPER CLIPS	Necessary	60.00 FS	*50.00 FS
30	6	*FRONT GRILLE CLIPS	Not Necessary	40.00 FS	*- FS
31	4	*FRONT RIGHT FENDER INNER COWLING CLIPS	Necessary	30.00 FS	*30.00 FS
32	10	*FRONT BUMPER LOWER GRILLE CLIPS	Not Necessary	40.00 FS	*- FS
33	2	*FRONT RIGHT PARKING SENSOR	Shorted	850.00 FS	*240.00 FS
34	1	*FRONT RIGHT TYRE	Not Necessary	500.00 FS	*- FS
35	1	*FRONT RIGHT SPORT RIM	Repair	1,250.00 FS	*- FS
36	1	*FRONT RIGHT QUARTER GLASS SEALANT	Not Necessary	80.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	41,212.20	9,914.80
- List Item Discount on L Items 25.00/25.00% (\$)	9,590.55	2,398.70

Total Parts (\$)	31,621.65	7,516.10
-------------------------	------------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR FOR PANEL BEATING,CUT,WELD,STRAIGHTEN FRONT RIGHT AFFECTED AREA AND REPLACE FRONT RIGHT DAMAGED PARTS	New	1,400.00	400.00
2	TO PUTTY AND SPRAY PAINTING FRONT RIGHT PORTION	New	1,400.00	700.00
3	TO CHECK WIRING AND FOCUS FRONT HEADLAMP	New	50.00	20.00
4	TO REMOVE AND INSTALL FRONT BONNET LOCK MECHANISM	New	80.00	0.00
5	TO APPLY ANTI RUST PROOFING TO FRONT RIGHT AFFECTED AREA	New	140.00	30.00
6	TO SYNCHRONISE THE FRONT PARKING SENSOR AND CHECK FOR FUNCTION	New	80.00	50.00
7	TO SYNCHRONISE FRONT RIGHT WING MIRROR FOR FUNCTION	New	120.00	0.00
8	TO TRANSFER FRONT RIGHT DOOR GLASS TO NEW DOOR	New	80.00	0.00
9	TO CHECK FRONT RIGHT DOOR CENTRAL LOCKING FOR FUNCTION	New	80.00	0.00
10	TO REMOVE AND INSTALL FRONT RIGHT QUARTER GLASS	New	80.00	0.00
11	TO REMOVE AND INSTALL FRONT RIGHT UNDERCARRIAGE PARTS	New	350.00	0.00
12	TO BALANCE FRONT RIGHT WHEEL	New	50.00	0.00
13	TO CONDUCT WHEEL ALIGNMENT	New	120.00	60.00
14	TOWING SERVICE	New	100.00	0.00
Gross Labour Cost (\$\$)			4,130.00	1,260.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >