

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21011448/UVY3N2**Date:** 22/11/2021**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMHCSNW00007482001

Claimant Vehicle No : SLS5809J **Insured Vehicle No :** SLU2901J

Date of Loss: 01/11/2021 Nature of Claim: TP Claim No: SNM21D206266/C02/TANKW

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLS5809J**

Make & Model: KIA CERATO K3, 1.6 (A) Engine No: G4FGGH672453

Reg. Date: 28/09/2017 (Man. Year: 2017) Chassis No: KNAFX411MJ5729736

Colour: White Odometer: 108830 km

Engine Capacity: 1591 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55R16 Rear Tyre Size: 205/55R16

Front Left Side: West Lake 6 mm Rear Left Side: West Lake 6 mm

Front Right Side: West Lake 6 mm Rear Right Side: West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,648.00	949.50	698.50	42.38
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,410.00	700.00	710.00	50.35
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	3,058.00	1,649.50	1,408.50	46.06
Approved Total (Overridden) (\$\$)		1,300.00		
(\$\$)	3,058.00	1,300.00	1,758.00	57.49
+ GST 7.00/7.00% (\$\$)	214.06	91.00	123.06	57.49
Nett Amount (\$\$)	3,272.06	1,391.00	1,881.06	57.49

INSPECTION

Date of Assignment: 17/11/2021

Date Inspected: 16/11/2021 Inspected At: Hock Wah Motor Workshop Pte Ltd (Bedok)
Blk 3011, Bedok Industrial Park E., #01-2008/2010/2012
Singapore 489977

Estimated Period of Repair: 2.0 days

Adjuster: MARCUS CHUA**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 19 Nov 2021)
Parts:	143	KIA CERATO K3 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLS5809J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Dented/Deformed	688.00 F	*688.00 FL
2	1		*REAR BUMPER LOWER GARNISH	Grazed	347.00 F	*347.00 FL
3	1		*REAR BUMPER REINFORCEMENT	Serviceable	313.00 F	*- FL
4	4		*REAR BUMPER CLIP	Necessary	20.00 F	*20.00 FL
5	1		*REVERSE SENSOR	Serviceable	280.00 FS	*- FS
6	1		*END PANEL (NPA)	Repair	0.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	1,648.00	1,055.00
- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00	105.50
Total Parts (\$\$)	1,648.00	949.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR TO REMOVE & REFIT NECESSARY PARTS	New	600.00	250.00
2	SPRAY PAINT ON THE AFFECTED AREAS	New	600.00	400.00
3	ANTI-RUST COATING	New	60.00	0.00
4	TO REMOVE & REFIT REVERSE SENSOR	New	150.00	50.00
Gross Labour Cost (\$\$)			1,410.00	700.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >