

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21011450/KTY3Q2**Date:** 09/03/2022**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNW00194172000	
Claimant Vehicle No :	SJX2192X	Insured Vehicle No :	SMG191R	
Date of Loss:	03/11/2021	Nature of Claim:	TP	Claim No: SNM21D206345/C01/CHEESC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJX2192X		Engine No:	G4KEAH713055
Make & Model:	KIA SORENTO, 2.2 (A)		Chassis No:	KNAKU811MA5075226
Reg. Date:	25/05/2010 (Man. Year: 2010)		Odometer:	171500 km
Colour:	Metallic Dark Green			
Engine Capacity:	2359 cc			
Market Value/New Car Price:	N/A			
Sum Insured (\$\$):	Market Value/New Car Price			

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/60Z R18	Rear Tyre Size:	235/60Z R18
Front Left Side:	Triangle 6 mm	Rear Left Side:	Continental 5 mm
Front Right Side:	Triangle 6 mm	Rear Right Side:	Continental 5 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,152.50	4,842.30	2,310.20	32.30
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,560.00	820.00	740.00	47.44
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	8,712.50	5,662.30	3,050.20	35.01
Approved Total (Overridden) (\$\$)		5,250.00		
(\$\$)	8,712.50	5,250.00	3,462.50	39.74
+ GST 7.00/7.00% (\$\$)	609.88	367.50	242.38	39.74
Nett Amount (\$\$)	9,322.38	5,617.50	3,704.88	39.74

INSPECTION

Date of Assignment:	26/02/2022	
Date Inspected:	23/11/2021	Inspected At: Ah Lim Motor Company (AMK) 10 Ang Mo Kio Industrial Park 2A, #01-09 AMK Autopoint Singapore 568047
Estimated Period of Repair:	4.0 days	

Adjuster: KENNETH KONG**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 07 Mar 2022)
Parts:	M1-SUV	KIA SORENTO 2.2 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJX2192X)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*RADIATOR GRILLE ASSY	Serviceable	290.00 FL	*- FL
2	1		*HEADLAMP RH	Cut / Mtg Cracked	2,059.00 FL	*2,059.00 FL
3	1		*HEADLAMP NOZZLE SET RH	Cracked	187.00 FL	*187.00 FL
4	1		*HEADLAMP NOZZLE COVER LH & RH	O/S Missing	198.00 FL	*99.00 FL
5	1		*HEADLAMP NOZZLE HOSE	Serviceable	67.00 FL	*- FL
6	1		*FRONT BUMPER	Cracked	645.00 FL	*645.00 FL
7	1		*FRONT BUMPER LOWER GRILLE	Serviceable	27.00 FL	*- FL
8	1		*FRONT BUMPER LOWER GARNISH	Cracked	709.00 FL	*709.00 FL
9	1		*FRONT BUMPER SIDE BRACKET SUPPORT RH	Distorted	26.00 FL	*26.00 FL
10	1		*FRONT BUMPER SIDE BRACKET UPPER RH	Serviceable	30.00 FL	*- FL
11	1		*FRONT BUMPER SIDE BRACKET REINFORCEMENT RH	Serviceable	19.00 FL	*- FL
12	8		*FRONT BUMPER RIVET	Necessary	24.00 FL	*24.00 FL
13	1		*FRONT BUMPER SPONGE	Cracked	106.00 FL	*106.00 FL
14	1		*FRONT BUMPER REINFORCEMENT	Repair	520.00 FL	*- FL
15	1		*FOGLAMP RH	Mtg Cracked	117.00 FL	*117.00 FL
16	1		*FOGLAMP COVER RH	Dented	27.00 FL	*27.00 FL
17	1		*FRONT FENDER WHEEL ARCH RH	Serviceable	116.00 FL	*- FL
18	1		*FRONT FENDER COWLING RH	Missing	92.00 FL	*92.00 FL
19	6		*FRONT FENDER COWLING CLIPS	Necessary	18.00 FL	*18.00 FL
20	1		*FRONT FENDER COWLING MUDGUARD RH	Serviceable	24.00 FL	*- FL
21	1		*WASHER TANK ASSY (WITH MOTOR)	Cracked	577.00 FL	*577.00 FL
22	1		*SIDE MIRROR ASSY RH (Scratched)	Not Consistent With The Impact	642.00 FL	*- FL
23	1		*FRONT DOOR OUTER HANDLE RH	Serviceable	215.00 FL	*- FL
24	1		*FRONT DOOR OUTER HANDLE BASE RH	Serviceable	215.00 FL	*- FL
25	1		*FRONT DOOR LOCK RH	Repair	264.00 FL	*- FL
26	1		*SUPPORT PANEL	Cracked	661.00 FL	*661.00 FL
27	1		*NUMBER PLATE	Serviceable	35.00 FS	*- FS
28	1		*RADIATOR COOLANT	Necessary	30.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	7,940.00	5,377.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	787.50	534.70
Total Parts (\$\$)	7,152.50	4,842.30

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISCONNECT AND CHECK ELECTRICAL WIRING WIRE SOCKETS AND ETC TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS ,TEST AND RECTIFY FOR PROPER FUNCTIONING	New	40.00	20.00
2	TO DISMANTLE AND TRANSFER DOOR FITTINGS AND MECHANISM SUCH AS POWER WINDOW MOTOR AND REGULATOR TO NEW DOOR /FACILITATE REPAIR	New	120.00	0.00
3	TO DISMANTLE ALL DAMAGED PARTS TO CUT & WELD TO KNOCK & REPAIR FRONT BONNET ,FRONT FENDER RH FRONT DOOR RH INNER PANELS AND AFFECTED AREAS TO REFIT LISTED PARTS BACK SAME	New	600.00	400.00
4	TO SPRAY FRONT BONNET ,FRONT BUMPER ,FRONT FENDER RH ,FRONT DOOR RH	New	800.00	400.00
Gross Labour Cost (\$\$)			1,560.00	820.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >