

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21011453/VGA3Q2**Date:** 20/05/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100215214
Claimant Vehicle No :	SLD1594H	Insured Vehicle No :	SCW9848E
Date of Loss:	05/11/2021	Nature of Claim:	TP
		Claim No:	3851746968SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLD1594H	Engine No:	HR12184404B
Make & Model:	NISSAN NOTE, 1.2 CVT (A)	Chassis No:	JN1TAAE12Z0972252
Reg. Date:	03/06/2016 (Man. Year: 2016)	Odometer:	164459 km
Colour:	Black		
Engine Capacity:	1198 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/60 R15	Rear Tyre Size:	185/60 R15
Front Left Side:	Giti 5 mm	Rear Left Side:	Giti 5 mm
Front Right Side:	Giti 5 mm	Rear Right Side:	Giti 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,228.18	1,406.40	1,821.78	56.43
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,450.00	880.00	1,570.00	64.08
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,678.18	2,286.40	3,391.78	59.73
Approved Total (Overridden) (S\$)		1,850.00		
(S\$)	5,678.18	1,850.00	3,828.18	67.42
+ GST 7.00/7.00% (S\$)	397.47	129.50	267.97	67.42
Nett Amount (S\$)	6,075.65	1,979.50	4,096.15	67.42
+ Loss of Use (5.0 x S\$60.00/day) (S\$)		300.00		
+ Doc/Search Fee (S\$)		31.45		
Nett Liability (S\$)		2,310.95		
Global Sum Settlement (S\$)		2,300.00		

INSPECTION

Date of Assignment:	09/11/2021		
Date Inspected:	09/11/2021	Inspected At:	Teamwork Garage Pte Ltd (HQ) 53 Ubi Ave 1 #01-24, Paya Ubi Industrial Park Singapore 408934
Estimated Period of Repair:	3.0 days		

Adjuster: Thevan Thomas Karthikesavan**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	528.00 FL	*460.00 FL
2	1		*REAR BUMPER RETAINER RH	Necessary	61.00 FL	*61.00 FL
3	1		*TAILLAMP RH	Serviceable	320.00 FL	*- FL
4	1		*REAR FENDER RH	Deformed	1,271.00 FL	*911.00 FL
5	1		*REAR FENDER INNER SHIELD RH	Distorted	64.00 FL	*64.00 FL
6	1		*REAR WHEEL HUB W BEARING RH	Serviceable	143.20 FL	*- FL
7	1		*REAR SHOCK ABSORBER RH	Serviceable	133.00 FL	*- FL
8	1		*RIM	Serviceable	500.00 FS	*- FS
9	1		*TYRE	Serviceable	400.00 FS	*- FS
10	1		*SET REAR BUMPER CLIP	Necessary	30.00 FS	*30.00 FS
11	1		*SET REAR FENDER INNER SHIELD CLIP	Necessary	30.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	3,480.20	1,556.00
- List Item Discount on L Items 10.00/10.00% (\$)	252.02	149.60
Total Parts (\$)	3,228.18	1,406.40

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	CHECK WIRING AND LIGHTING SYSTEM	New	150.00	20.00
2	COMPUTERIZE AND CHECK WHEEL ALIGNMENT	New	200.00	0.00
3	REMOVE AND REFIT UNDERCARRIAGE	New	200.00	0.00
4	REMOVE AND REFIT REVERSE SENSOR	New	150.00	30.00
5	PANEL BEATING ON AFFECTED AREAS	New	800.00	400.00
6	SPRAY PAINTING ON AFFECTED AREAS	New	800.00	400.00
7	APPLY ANTI RUST ON AFFECTED AREAS	New	150.00	30.00
			Gross Labour Cost (\$)	2,450.00
				880.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >