

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21011455/BGA3Q2**Date:** 15/06/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1700013108
Claimant Vehicle No :	SLU8753E	Insured Vehicle No :	SGX8455J
Date of Loss:	04/11/2021	Nature of Claim:	TP
		Claim No:	1390290747SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLU8753E	Engine No:	MR20168401C
Make & Model:	NISSAN X-TRAIL, 2.0 CVT (A)	Chassis No:	JN1JANT32Z0010516
Reg. Date:	16/12/2017 (Man. Year: 2017)	Odometer:	49148 km
Colour:	Silver		
Engine Capacity:	1997 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/55 R19	Rear Tyre Size:	225/55 R19
Front Left Side:	Bridgestone 5 mm	Rear Left Side:	Bridgestone 5 mm
Front Right Side:	Bridgestone 5 mm	Rear Right Side:	Bridgestone 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,075.03	6,122.03	6,953.00	53.18
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,300.00	1,460.00	2,840.00	66.05
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	17,375.03	7,582.03	9,793.00	56.36
Approved Total (Overridden) (S\$)		6,050.00		
(S\$)	17,375.03	6,050.00	11,325.03	65.18
+ GST 7.00/7.00% (S\$)	1,216.25	423.50	792.75	65.18
Nett Amount (S\$)	18,591.28	6,473.50	12,117.78	65.18
+ Car Rental (7.0 x S\$150.00/day) (S\$)		1,050.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		7,530.95		
Global Sum Settlement (S\$)		7,500.00		

INSPECTION

Date of Assignment:	09/11/2021	Team Autopro Pte Ltd - Sin Ming (HQ)
Date Inspected:	09/11/2021 Inspected At:	160 SIN MING DRIVE #02-12 SIN MING
		AUTOCITY
		Singapore 575722
Estimated Period of Repair:	5.0 days	

Adjuster: Lim Teow Guan**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Dented	4,258.00 FL	*4,200.00 FL
2	1		*TAILGATE LOGO	Necessary	286.30 FL	*76.10 FL
3	1		*TAILGATE EMBLEM X-TRAIL	Necessary	201.40 FL	*88.30 FL
4	1		*TAILGATE WEATHERSTRIP	Not Damaged	418.40 FL	*- FL
5	1		*TAILGATE WINDSCREEN MOULDING	Necessary	285.70 FL	*179.40 FL
6	1		*REAR BUMPER	Broken	990.80 FL	*693.50 FL
7	1		*REAR BUMPER OUTER CHROME MOULDING	Broken	244.00 FL	*171.00 FL
8	2		*REAR BUMPER SIDE RETAINER	Necessary	360.00 FL	*66.00 FL
9	1		*REAR BUMPER CENTRE GARNISH	No such part	85.60 FL	*- FL
10	2		*REAR BUMPER BRACKET	Repair	397.60 FL	*- FL
11	1		*REAR BUMPER REINFORCEMENT	Bent	893.40 FL	*533.80 FL
12	1		*REAR BUMPER REINFORCEMENT BRACKET	O/S Cracked	734.20 FL	*367.10 FL
13	1		*REAR BUMPER REFLECTOR RH	Broken	286.30 FL	*71.50 FL
14	1		*REAR END PANEL	Not Damaged	781.10 FL	*- FL
15	1		*REAR END PANEL TOP GARNISH	Not Damaged	183.50 FL	*- FL
16	1		*REAR FENDER RH	Repair	1,426.10 FL	*- FL
17	1		*REAR FENDER ARCH GARNISH RH	Not Damaged	325.00 FL	*- FL
18	1		*REAR FENDER AIR VENTS RH	Not Damaged	78.90 FL	*- FL
19	1		*REAR FENDER INNER TRIM BOARD RH	Not Damaged	580.40 FL	*- FL
20	1		*SUNDRIES	Not Necessary	80.00 FS	*- FS
21	1		*TAILGATE WINDSCREEN CLIPS	Not Necessary	50.00 FS	*- FS
22	1		*TAILGATE WINDSCREEN SEALANT	Necessary	100.00 FS	*30.00 FS
23	1		*TAILGATE WINDSCREEN INNER SEAL	Necessary	100.00 FS	*30.00 FS
24	1		*TAILGATE WINDSCREEN PRIMER AND CLEANER	Not Necessary	80.00 FS	*- FS
25	1		*REAR BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
26	1		*REAR BUMPER OUTER CHROME MOULDING CLIPS	Not Necessary	50.00 FS	*- FS
27	1		*REAR BUMPER OUTER GARNISH CLIPS	No such part	50.00 FS	*- FS
28	2		*REAR BUMPER REVERSE SENSOR	Scratched	500.00 FS	*200.00 FS
29	1		*REAR END PANEL SEALANT	Not Necessary	100.00 FS	*- FS
30	1		*REAR END PANEL TOP GARNISH CLIPS	Not Necessary	50.00 FS	*- FS
31	1		*REAR FENDER SEALANT	Not Necessary	100.00 FS	*- FS
32	1		*REAR FENDER INNER COWLING CLIPS	Not Necessary	50.00 FS	*- FS
33	1		*REAR FENDER ARCH GARNISH CLIPS	Not Necessary	50.00 FS	*- FS
34	1		*REAR FENDER INNER TRIM BOARD CLIPS	Not Necessary	50.00 FS	*- FS
35	1		*REAR NUMBER PLATE W/CASING	Broken	80.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	14,356.70	6,766.70
- List Item Discount on L Items 10.00/10.00% (\$\$)	1,281.67	644.67
Total Parts (\$\$)	13,075.03	6,122.03

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	R&R TAILGATE COMPONENT	New	150.00	80.00
2	R&R TAILGATE WINDSCREEN	New	250.00	120.00
3	R&R REAR BUMPER REVERSE SENSOR	New	100.00	60.00
4	CHECK WIRING	New	100.00	0.00
5	UPHOLSTERY	New	300.00	0.00
6	PANEL BEATING	New	1,600.00	600.00
7	RUST PROOFING	New	200.00	0.00
8	SPRAY PAINTING	New	1,600.00	600.00
Gross Labour Cost (\$)			4,300.00	1,460.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >