

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21011456/BUY3Q2
Date: 20/12/2021REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNA00120112100
Claimant Vehicle No :	SJU9121X	Insured Vehicle No :	SFR4690R
Date of Loss:	07/11/2021	Nature of Claim:	TP
		Claim No:	SNM21D206388/C02/TANKL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJU9121X	Engine No:	LF10903545
Make & Model:	MAZDA MX-5, 2.0 RHT (NC3) (A)	Chassis No:	JM0NC30F2A0201803
Reg. Date:	04/01/2010 (Man. Year: 2009)	Odometer:	136392 km
Colour:	Yellow		
Engine Capacity:	1999 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	225/45 R17	Rear Tyre Size:	225/45 R17
Front Left Side:	Michelin 5 mm	Rear Left Side:	Michelin 5 mm
Front Right Side:	Michelin 5 mm	Rear Right Side:	Michelin 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,056.34	6,106.56	4,949.78	44.77
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,590.00	2,420.00	3,170.00	56.71
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	16,646.34	8,526.56	8,119.78	48.78
Approved Total (Overridden) (S\$)		6,800.00		

	(S\$)	16,646.34	6,800.00	9,846.34	59.15
	+ GST 7.00/7.00% (S\$)	1,165.24	476.00	689.24	59.15
	Nett Amount (S\$)	17,811.58	7,276.00	10,535.58	59.15

INSPECTION

Date of Assignment: 10/12/2021

Date Inspected: 09/11/2021

Inspected At:

Bifrost Auto Pte Ltd (Kaki Bukit)
8 Kaki Bukit Ave 4, #01-49, Premier @ Kaki Bukit
Singapore 415875

Estimated Period of Repair: 9.0 days

Adjuster: Lim Teow Guan**Manager:** Tan Hui Zhen

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 17 Dec 2021)	
Parts:	N/A	MAZDA MX-5 2.0 RHT (NC3) (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJU9121X)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Dented	1,208.40 FL	*1,125.00 FL
2	1		*BOOTLID CENTRE EMBLEM	Necessary	55.80 FL	*29.20 FL
3	1		*BOOTLID MX5 EMBLEM	Necessary	90.60 FL	*38.00 FL
4	1		*BOOTLID LOCK	Jammed	273.80 FL	*247.00 FL
5	1		*REAR BUMPER	Broken	1,451.93 FL	*987.00 FL
6	1		*REAR BUMPER LOWER GARNISH	No such part	452.30 FL	*- FL
7	1		*REAR BUMPER RH SIDE RETAINER	Necessary	63.50 FL	*37.60 FL
8	1		*REAR BUMPER LH SIDE RETAINER	Necessary	63.50 FL	*37.60 FL
9	1		*REAR BUMPER LH SIDE BEAM	No such part	115.80 FL	*- FL
10	1		*REAR BUMPER REINFORCEMENT	Dented	467.80 FL	*467.80 FL
11	1		*LH TAILLAMP ASSY	Broken	535.10 FL	*535.10 FL
12	1		*LH TAILLAMP SPONGE GASKET	Necessary	22.00 FL	*22.00 FL
13	1		*LH TAILLAMP PANEL	Dented	185.30 FL	*185.30 FL
14	1		*RH TAILLAMP ASSY	Not Damaged	505.10 FL	*- FL
15	1		*RH TAILLAMP SPONGE GASKET	Not Necessary	22.00 FL	*- FL
16	1		*REAR WINDSCREEN GLASS RUBBER SEAL	Not Necessary	111.00 FL	*- FL
17	1		*REAR LH FENDER	Dented	933.70 FL	*828.00 FL
18	1		*REAR LH FENDER INNER TRIM	Broken	420.30 FL	*326.95 FL
19	1		*REAR LH FENDER SPLASH SHIELD	Broken	380.80 FL	*158.00 FL
20	1		*END PANEL	Dented	453.15 FL	*453.15 FL
21	1		*END PANEL INNER GARNISH	Broken	194.60 FL	*138.00 FL
22	1		*SPARE TYRE TOP COVER BOARD	Not Damaged	766.80 FL	*- FL
23	1		*EXHAUST SILENCER CHROME TIP	Bent	178.60 FL	*100.00 FL
24	1		*EXHAUST SILENCER	Bent	1,405.60 FL	*582.00 FL
25	1		*EXHAUST SILENCER GASKET	Necessary	71.70 FL	*50.00 FL
26	1		*REAR LH WHEEL BEARING	Not Damaged	405.20 FL	*- FL
27	1		*REAR LH SHOCK ABSORBER	Not Damaged	233.90 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
28	1		*REAR LH KNUCKLE ARM	Not Damaged	612.30 FL	*- FL
29	1		*REAR LH LOWER ARM	Not Damaged	435.60 FL	*- FL
30	1		*REAR NUMBER PLATE	Not Damaged	70.00 FS	*- FS
31	1		*SET REAR BUMPER CLIPS	Necessary	70.00 FS	*30.00 FS
32	1		*REAR WINDSCREEN GLASS SEALANT	Not Necessary	70.00 FS	*- FS
33	1		*REAR WINDSCREEN GLASS INNER SEAL	Not Necessary	50.00 FS	*- FS
34	1		*REAR LH FENDER JOINT SEALANT	Necessary	70.00 FS	*30.00 FS
35	1		*REAR LH FENDER INNER TRIM CLIPS	Necessary	55.00 FS	*30.00 FS
36	1		*END PANEL JOINT SEALANT	Necessary	70.00 FS	*30.00 FS
37	1		*REAR COMPARTMENT PANEL	Dented	1,098.00 FL	*1,098.00 FL
38	1		*REAR COMPARTMENT PANEL JOINT SEALANT	Necessary	30.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	13,699.18	7,595.70
- List Item Discount on L Items 20.00/20.00% (\$)	2,642.84	1,489.14
Total Parts (\$)	11,056.34	6,106.56

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR CHARGES TO REMOVE ,CHECK ,REPLACE AND REINSTALL DAMAGES BODYPARTS TO PANEL BEATING ,CUT/WELD AND RE-ALIGN ALL AFFECTED PANELS	New	1,200.00	1,000.00
2	SPRAY PAINTING ON AFFECTED PANELS	New	1,200.00	600.00
3	CHECK ALL WIRING AND ALL LIGHTING SYSTEM	New	70.00	0.00
4	APPLY RUST COATING CHEMICAL ON AFFECTED PANELS	New	80.00	0.00
5	REMOVE AND REINSTALL REAR WINDSCREEN GLASS TO ASSIST REPAIR	New	200.00	0.00
6	REMOVE AND REPLACE REAR INNER TRIMS ,GARNISH ,ROOF LINING SEATS AND BOARDS TO ASSIST REPAIR	New	280.00	0.00
7	REMOVE AND REINSTALL FUEL TANK ,PIPES HOSES AND SENSORS TO ASSIST REPAIR	New	180.00	0.00
8	REMOVE AND REPLACE REAR UNDERCARRIAGE PARTS TO ASSIST REPAIR	New	300.00	0.00
9	CONDUCT AND ADJUST ALIGNMENT SYSTEM	New	100.00	0.00
10	REMOVE AND REPLACE EXHAUST SILENCER AND CHROME LIP TO ASSIST REPAIR	New	180.00	120.00
11	CUT /WELD AND REPLACE REAR COMPARTMENT PANEL AND ALL AFFECTED AREAS	New	800.00	400.00
12	RESPRAY REAR COMPARTMENT PANEL AND ALL AFFECTED AREAS	New	800.00	200.00
13	REMOVE AND REAR SEATS AND CARPET TO ASSIST REPAIR	New	200.00	100.00
Gross Labour Cost (S\$)			5,590.00	2,420.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >