

ASS. REC. BY: Tan J H

REF: 04/4192101457/T.M3

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 4185K

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SMR228L Yr Regn: 2008 / July

Type: M.Cat / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Porsche 911 Carrera c.c. 3614

Colour: Orange A/C: Insured / Std / NI / NA

Sp. Reading: 88438 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: _____

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / SRIm / STD A/RIm or

Tyre Size: _____

F: _____

R: 305/30R19

BS / DUN / EXNOVA / GY / FS / LIZA / MG / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

R/Bal. 6 mm

L/Bal. 6 mm

D.O.A. _____

Survey held at J.E.W. Auto.

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

R/Bal. 6 mm

L/Bal. 6 mm

D.O.I. 6/4/21

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Report Format: _____

Lump Sum / L.B.A. (?) _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee:

☐

Site Insp (\$ _____)

☐

Interview (\$ _____)

☐

Tech. Invs (\$ _____)

☐

Weekend (\$ _____)

Survey Fee: _____

Transportation: _____

\$ + RS. \$ _____

Photos _____

Others _____

TOTAL _____



Estimation

Date 08/11/2021
 Vehicle SMR 228 L
 Make/Model PORSCHE 911 CARRERA
 Chassis No. WP0ZZZ99Z6S701288

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

No.	Description	Unit	Unit Price	Amount
	Parts Replacment			
1	REAR BOOTLID <i>bt</i> ✓	1		\$ -
2	REAR BOOTLID TOP VENT LID <i>X</i>	1		\$ -
3	REAR BOOTLID EMBLEM 'PORSCHE' <i>net</i> ✓	1		\$ -
4	REAR BOOTLID EMBLEM '911' <i>net</i> ✓	1		\$ -
5	REAR BOOTLID EMBLEM 'CARRERA' <i>net</i> ✓	1		\$ -
6	REAR BOOTLID DAMPER L+R <i>X</i>	2		\$ -
7	REAR BOOTLID HINGE MECHANISM CENTER L+R <i>X</i>	2		\$ -
8	REAR BOOTLID HINGE MECHANISM SIDE L+R <i>X</i>	2		\$ -
9	REAR BOOTLID INNER TRIM <i>X</i>	1		\$ -
10	REAR BOOTLID AIR INTAKE TOP <i>X</i>	1		\$ -
11	REAR BOOTLID AIR INTAKE BOTTOM HOSE <i>X</i>	1		\$ -
11	REAR BOOTLID FAN COWLING <i>X</i> ✓	1		\$ -
12	REAR BOOTLID FAN BLADE <i>X</i>	1		\$ -
13	REAR BOOTLID FAN MOTOR <i>X</i>	1		\$ -
14	REAR BOOTLID CATCH <i>X</i>	1		\$ -
15	REAR BOOTLID LOCK MECHANISM <i>?</i>	1		\$ -
16	REAR BOOTLID WEATHERSTRIP <i>?</i>	1		\$ -
16	REAR TAILLAMP L+R <i>LH X RH int</i> ✓	2	\$ 520.00	\$ 1,040.00
17	REAR TAILLAMP PANEL L+R <i>X</i>	2		\$ -
18	REAR BUMPER <i>int</i> ✓	1	\$ 2,501.80	\$ 2,501.80
19	REAR BUMPER RETAINER L+R <i>int</i> ✓	2		\$ -
20	REAR BUMPER RETAINER SMALL L+R <i>X</i>	2		\$ -
21	REAR BUMPER SPONGE <i>X</i>	1		\$ -
22	REAR BUMPER REINFORCEMENT BAR <i>bt</i> ✓	1		\$ -
23	REAR BUMPER BRACKET L+R <i>X</i>	2		\$ -
24	REAR BUMPER REVERSE SENSOR L+R <i>X</i>	2		\$ -
25	REAR BUMPER VRN LAMP L+R <i>int</i> ✓	2		\$ -
26	REAR BUMPER REVERSE CAMERA <i>ds</i> ✓	1		\$ -
27	REAR END PANEL <i>bt</i> ✓	1	\$ 842.67	\$ 842.67
28	REAR END PANEL ENGINE COVER <i>X</i>	1		\$ -
29	REAR EXHAUST L+R <i>X</i>	2		\$ -
30	REAR EXHAUST CHROME TIP L+R <i>X</i>	2	\$ 478.20	\$ 956.40
31	REAR EXHAUST HEATSHIELD <i>bt</i> ✓	1		\$ -
32	REAR EXHAUST MANIFOLD L+R <i>LH X RH</i> <i>?</i>	2		\$ -

				Total	\$	5,340.87
				Less 10%	\$	534.09
				Total	\$	4,806.78

S/Nett Items						
1	REAR BOOTLID INNER TRIM CLIPS	10	\$	10.00	\$ X	100.00
2	REAR TAILLAMP CLIPS	10	\$	10.00	\$ 20 net ✓	100.00
3	REAR BUMPER CLIPS	10	\$	10.00	\$ 30 net ✓	100.00
4	REAR END PANEL SEALANT	1	\$	120.00	\$ 40 net ✓	120.00
5	REAR TAILLAMP PANEL SEALANT	1	\$	120.00	\$ X	120.00
				Total	\$	540.00

LABOUR						
1	PANEL BEATING ON AFFECTED AREAS	1		1800	\$ 700.	1,800.00
2	SPRAY PAINT ON AFFECTED AREAS	1		1800	\$ 700	1,800.00
3	TO RNR REAR EXHAUST	1		400	\$ X	400.00
4	TO CHECK WIRING AND TAIL LAMP FUNCTION	1		150	\$ 30.	150.00
5	TO RNR REAR INNER TRIM AND UPHOISTERY	1		400	\$ 60	400.00
6	TO CHECK WATER LEAK	1		300	\$ X	300.00
7	TO PERFORM DIAGNOSTIC AND CLEAR FAULTS	1		600	\$ X	600.00
8	TO RNR REAR TAILGATE MECHANISM	1		400	\$ 60.	400.00
9	TO RNR REAR REVERSE SENSOR AND CHECK FUNCTION	1		300	\$ 30.	300.00
10	TO PERFORM RUST PROOFING	1		200	\$ 30.	200.00
11	TO RNR REAR BOOTLID REAR VENT LID AND CHECK FUNCTION	1		400	\$ 700.	400.00
12	TO RNR REAR BOOTLID FAN AND CHECK FUNCTION	1		400	\$ 500.	400.00
13	TO CHECK AND ENSURE NO OVERHEATING ON ENGINE	1		400	\$ X	400.00
				Total Labour	\$	7,550.00
				Parts Replacement Amount	\$	5,346.78
				Total Amount	\$	12,896.78

Tanpin 97495749

'wp' 10/4/21 @ 4:15 pm

ALS Runy after repair

Tanpin @ khantawon.

6 days