

ASS. BY:

REF: CC4/GRB21011459/Dgs³

ASSIGNMENT

From: _____ Date: _____

Estimate Cost: _____

OD / RES / TP RES / OD RES / EVA / RV / MV

To Inspect Vehicle No: _____

at V/O of _____

at _____

Insurance _____

Policy No. _____

Claims to _____

Sum Insured _____

Excess _____

(Check record)

Make Over _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. of Market Value: _____

IDAC Accident Report _____ Consistent? : Yes or No

GIA / PR Seen _____ Consistent? : Yes or No

Est. Repairs: 7 days Res.: Yes or No

Lump Sum: 20 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SMZ 7876C Yr Regn: May 2021

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda Shuttle CC 1496

Colour: silver A/C: Insured / Std / RE / NA

Sp. Reading: 8850 T/Radio: Insured / Std / RE / NA

Eng/No: L15B6024232

C/No: GK82103660

Gen. Cond: Good / Fair / Poor / Burnt

Steering: in order / Jammed / Leaked / Burnt or

Brake: in order / Jammed / Leaked / Burnt or

Mod: RE / Std / STD A/R or

Tyre Size: F: 185/60 R15
R: 11

BS / DUN / EXNOVA / GY / FS / LZA / MIC / OHTSU / PRI / SUZUKI /

TOYO / YOKO or Bridgestone

Front	Rear
R/Bal: <u>S</u> mm	R/Bal: <u>S</u> mm
L/Bal: <u>S</u> mm	L/Bal: <u>S</u> mm

D.O.A. 07/11/2021 D.O.I. 09/11/2021

Survey held at CS ong AMIC

Des. of Damages: Front / Rear / O/S / N/S / LAC / Roof top or

O/S Front

The W/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>TU SML 8865B</u>
	<u>MV 95K</u>
	<u>LTA 42K</u>
	<u>NL 53K</u>

Date/Time, File Pass to?

☐ : Prel. Report

☐ : Final Report

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

S + RS \$

Acc Fee: ☐ : Site Insp (\$)

1)

Date/Time, File Return to?

2)