



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLN 2036T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR RH DOOR	TO REPAIR SEE LABOUR	1,025.45	-
2	REAR RH DOOR HINGES (TOP & LOWER)	SERVICEABLE	106.60	-
1	REAR RH DOOR LOCK STRIKER	SERVICEABLE	52.25	-
1	REAR RH DOOR MECHANISM LOCK	SERVICEABLE	339.85	-
1	ROCKER RH SIDE SKIRTING	CRACKED	263.95	263.95
2	ROCKER RH SIDE SKIRTING RETAINER 'CENTER'	NECESSARY	62.00	62.00
1	ROCKER RH SIDE SKIRTING RETAINER 'FRONT'	NECESSARY	25.00	25.00
1	ROCKER RH SIDE SKIRTING RETAINER 'REAR'	NECESSARY	28.00	28.00
1	REAR RH FENDER	TO REPAIR SEE LABOUR	1,120.00	-
1	REAR RH FENDER INNER SHIELD	SERVICEABLE	150.00	-
1	REAR RH KNUCKLE BEARING	JAMMED	465.75	465.75
1	REAR BUMPER	TO REPAIR SEE LABOUR	950.00	-
2	REAR BUMPER CENTER RETAINER L/R	SERVICEABLE	80.00	-
2	REAR BUMPER SIDE RETAINER L/R	SERVICEABLE	100.00	-
	LESS 10% DISCOUNT		-	-84.47
			4,768.85	760.23
<u>SPECIAL NETT ITEMS</u>				
1	SET ROCKER RH SIDE SKIRTING CLIPS (SN)	NECESSARY	30.00	30.00
1	SET REAR RH FENDER INNER SHIELD CLIPS (SN)	NOT NECESSARY	30.00	-
1	REAR RH 16" SPORT RIM (SN)	CUT	680.00	680.00
1	REAR RH 205/55R16 SPORT TYRE (SN)	SERVICEABLE	480.00	-
			1,220.00	710.00
<u>LABOUR</u>				
	TO REMOVE, REINSTALL ELECTRICAL WIRING HARNESS, CHECK LIGHTING.	NOT NECESSARY	120.00	-
	TO RESET SYSTEM AFTER REPAIR WORKS.	NOT NECESSARY	250.00	-
	TO RE-SPRAY PAINTING ON THE CHANGE BODYPARTS, REPAIR PORTION, AND WHERE CONSISTENT TO THE ACCIDENT.		1,700.00	800.00

Report Ref No. CS1/LAW21011461/Gqy3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO PROVIDE LABOUR TO CHANGE THE ABOVE DAMAGED BODYPARTS, REPAIR, BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT. INCLUSIVE OF THE REPAIR OF REAR RH DOOR, REAR RH FENDER AND REAR BUMPER.		1,500.00	400.00
	TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLACED PANEL.	NOT NECESSARY	120.00	-
			3,690.00	1,200.00
GRAND TOTAL			9,678.85	2,670.23
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,100.00

Report Ref No. CS1/LAW21011461/Gqy3e2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.