

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG21011465/AES3Q2**Date:** 20/06/2022**REFERENCE**

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:
Claimant Vehicle No : SMD3270S **Insured Vehicle No :** SLA9358L
 Date of Loss: 03/11/2021 Nature of Claim: TP Claim No: 0863753681SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMD3270S**
 Make & Model: HYUNDAI ELANTRA, 1.6 (A) Engine No: G4FGJU236529
 Reg. Date: 15/08/2018 (Man. Year: 2018) Chassis No: KMHD841CMJU728126
 Colour: Silver Odometer: 56532 km
 Engine Capacity: 1591 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15
 Front Left Side: Yokohama 6 mm Rear Left Side: Yokohama 6 mm
 Front Right Side: Yokohama 6 mm Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,438.40	1,549.68	4,888.72	75.93
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,440.00	970.00	3,470.00	78.15
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,878.40	2,519.68	8,358.72	76.84
Approved Total (Overridden) (S\$)		2,000.00		
(S\$)	10,878.40	2,000.00	8,878.40	81.61
+ GST 7.00/7.00% (S\$)	761.49	140.00	621.49	81.61
Nett Amount (S\$)	11,639.89	2,140.00	9,499.89	81.61
+ Car Rental (4.0 x S\$100.00/day) (S\$)		400.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		2,547.45		

INSPECTION

Date of Assignment: 08/11/2021
 Date Inspected: 08/11/2021 Inspected At: Xin Hua Workshop Pte Ltd (HQ)
 23 Kaki Bukit Ave 4 #04-01
 Singapore 415933
 Estimated Period of Repair: 3.0 days

Adjuster: ADRIAN LING**Manager:** Asher Sng Rong Yi*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and*

ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Not Necessary	1,783.50 FL	*- FL
2	1		*BOOTLID SMART KEY ANTENNA	Not Necessary	198.70 FL	*- FL
3	1		*BOOTLID BOOT RELEASE ANTENNA	Not Necessary	198.60 FL	*- FL
4	1		*BOOTLID INNER TRIM	Not Necessary	406.20 FL	*- FL
5	1		*BOOTLID LAMPS	Not Necessary	398.60 FL	*- FL
6	1		*BOOTLID LAMPS INNER SEALER	Not Necessary	35.00 FL	*- FL
7	1		*BOOTLID EMBLEM ELANTRA	Not Necessary	95.30 FL	*- FL
8	1		*BOOTLID EMBLEM S	Not Necessary	72.30 FL	*- FL
9	1		*BOOTLID LOGO	Not Necessary	95.40 FL	*- FL
10	1		*BOOTLID INNER LOCK	Not Necessary	285.90 FL	*- FL
11	1		*BOOTLID LOWER LATCH	Not Necessary	45.20 FL	*- FL
12	1		*BOOTLID WEATHERSTRIP	Not Necessary	198.60 FL	*- FL
13	1		*REAR BUMPER	Deformed	645.30 FL	*569.00 FL
14	1		*REAR BUMPER LOWER	Deformed	297.60 FL	*297.60 FL
15	2		*REAR BUMPER REFLECTORS	Not Necessary	191.20 FL	*- FL
16	2		*REAR BUMPER RETAINERS	Not Necessary	173.40 FL	*- FL
17	1		*REAR BUMPER REINFORCEMENT	Dented	378.10 FL	*378.10 FL
18	3		*REAR REINFORCEMENT BRACKETS	Not Necessary	269.10 FL	*- FL
19	1		*REAR BUMPER LOWER COVERS (RH)	Torn	196.30 FL	*196.30 FL
20	1		*TAILLAMPS (RH)	Cracked	423.60 FL	*423.60 FL
21	1		*TAILLAMPS INNER SEALER	Necessary	35.00 FL	*35.00 FL
22	1		*REAR FENDER INNER COWLING	Not Necessary	198.60 FL	*- FL
23	1		*REAR END PANEL	Repair	585.90 FL	*- FL
24	1		*REAR END PANEL TOP GARNISH	Not Necessary	215.60 FL	*- FL
25	1		*SET REAR NUMBER PLATE WITH CASING	Not Necessary	50.00 FS	*- FS
26	1		*SET REAR BUMPER CLIPS	Necessary	30.00 FS	*30.00 FS
27	1		*SET REAR END PANEL TOP GARNISH CLIPS	Not Necessary	30.00 FS	*- FS
28	1		*SET REVERSE SENSORS	Not Necessary	250.00 FS	*- FS
29	1		*SET TAILLAMP CLIPS	Not Necessary	30.00 FS	*- FS
30	1		*SET REAR FENDER INNER COWLING	Not Necessary	30.00 FS	*- FS
31	2		*END PANEL INSULATOR SEAL	Not Necessary	80.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	7,923.00	1,929.60
- List Item Discount on L Items 20.00/20.00% (\$)	1,484.60	379.92
Total Parts (\$)	6,438.40	1,549.68

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO RENEW DAMAGED PARTS ,REPLACE ,BEAT ,WELD ,REALIGN AND ALIGNE ALL PARTS	New	1,600.00	400.00
2	TO RESPRAY AFFECTED AREAS	New	1,600.00	400.00
3	TO TUFFCOAT AFFECTED AREA	New	200.00	30.00
4	TO REMOVE/REFIT INTERIOR UPHOLSTERY	New	150.00	0.00
5	TO APPLY SEALANT AND UNDERCOATING TO THE AFFECTED AREAS	New	350.00	60.00
6	TO REMOVE/REFIT WIRING CHECKS ON REAR TAILLAMP	New	120.00	30.00
7	TO CONDUCT WATER LEAKAGE TEST	New	150.00	0.00
8	TO REMOVE/REPLACE REVERSE SENSORS AND DISTANCE SETTLING	New	150.00	50.00
9	TO REMOVE /TRANSFER & REPLACE BOOTLID MECHANISM	New	120.00	0.00
			Gross Labour Cost (\$\$)	4,440.00
				970.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >