



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 7291U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	FRONT RH SIDE MIRROR ASSY	BROKEN	586.30	586.30
1	FRONT RH SIDE MIRROR GLASS	BROKEN	75.90	75.90
1	FRONT RH DELTA CHROME GARNISH	NOT NECESSARY	102.30	-
	LESS 20% DISCOUNT		-152.90	-132.44
			611.60	529.76
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	FRONT DOOR "COMFORT DELGRO" STICKER (SN)	NOT NECESSARY	140.00	-
			140.00	-
	<b><u>LABOUR</u></b>			
	TO RUST PROOFING OF THE AFFECTED AREA.	NOT NECESSARY	160.00	-
	TO DIAGNOSTIC, CHECK WIRING AND LIGHTING SYSTEM AND CLEAR FAULT CODE.		240.00	30.00
	TO RESPRAY FRONT DOOR PANEL.	NOT NECESSARY	250.00	-
	TO RESPRAY FRONT SIDE MIRROR.		250.00	80.00
	TO STRAIGHTEN AND PANEL BEAT OF ACCIDENT AREA.		800.00	100.00
			1,700.00	210.00
	<b>GRAND TOTAL</b>		<b>2,451.60</b>	<b>739.76</b>
	<b>RECOMMENDED COST OF REPAIRS</b>			<b>739.76</b>

Report Ref No. CS/AWA21011466/Euf3e2

CHEN TSUE YEE

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.