



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
ALLIED WORLD ASSURANCE COMPANY LTD (SINGAPORE BRANCH) 60 ANSON ROAD #08-01 (8th FLOOR) MAPLETREE ANSON SINGAPORE 079914		Ref: CS/AWA21011466/Euf3e2 Date: 18/11/2021 Code: AWA	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	XE 5506P	Veh. Inspected	SHC 7291U
Policy No.	BVFCB0007172114	Coverage (\$)	0.00
Claim No.	NSV2100149/HLF	Excess (\$)	0.00
Assign From	STELLA GOH	Assign Date	10/11/2021
2. Vehicle Particulars & Condition			
Make & Model	HYUNDAI I40	c.c	1685
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	KMHLB41UMGU093575	Colour	YELLOW
Odometer	840638 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	FAIR		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	205/60 R16	FIRENZA	4 mm
L/H Front Tyre	205/60 R16	FIRENZA	4 mm
R/H Rear Tyre	205/60 R16	FIRENZA	4 mm
L/H Rear Tyre	205/60 R16	FIRENZA	4 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	08/11/2021	Inspection Date	10/11/2021
Survey held at	31 Corporation Rd, Singapore 649806		
Repairer	DING AUTOMOTIVE PTE LTD		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days	