



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJS 8913U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT BUMPER	NOT NECESSARY	895.93	-
2	BUMPER RETAINER @\$38.50	NOT NECESSARY	77.00	-
1	LH FRONT FENDER	DENTED	675.63	675.63
1	LH FRONT FENDER UNDERGARNISH	TORN	220.70	220.70
1	LH FRONT DOOR	DENTED	1,885.73	1,481.00
1	LH FRONT DOOR PROTECTOR	DEFORMED	1,087.55	594.00
1	LH REAR DOOR	TO REPAIR SEE LABOUR	1,984.32	-
1	LH REAR DOOR PROTECTOR	TO REPAIR SEE LABOUR	850.96	-
1	LH REAR FENDER	TO REPAIR SEE LABOUR	1,211.70	-
1	LH FRONT ABSORBER	BENT	469.47	469.47
1	LH KNUCKLE ARM	DAMAGED	559.79	559.79
1	LH LOWER ARM	BENT	420.86	420.86
1	LH WHEEL BEARING	DAMAGED	531.59	381.00
1	LH SIDE MIRROR COMPLETE	DAMAGED	846.68	846.68
	LESS 25% DISCOUNT		-	-1,412.28
			11,717.91	4,236.85
<u>SPECIAL NETT ITEMS</u>				
1	BUMPER CLIP (SN)	NOT NECESSARY	50.00	-
8	LH FRONT DOOR PROTECTOR CLIP @\$7.50 (SN)	NECESSARY	60.00	20.00
8	LH REAR DOOR PROTECTOR CLIP @\$7.50 (SN)	NOT NECESSARY	60.00	-
1	LH RIM (SN)	CUT	650.00	400.00
1	LH FENDER INNER GARNISH CLIP (SN)	NECESSARY	60.00	30.00
			880.00	450.00
<u>LABOUR</u>				
	TO KNOCK AND CHANGE PARTS.INCLUSIVE OF THE REPAIR OF LH REAR DOOR,LH REAR DOOR PROTECTOR AND LH REAR FENDER.		1,200.00	600.00
	TO SPRAY FRONT BUMPER,LH FRONT FENDER,LH FRONT AND REAR DOOR,REAR FENDER.		1,500.00	1,100.00

Report Ref No. CS/AGI21011467/Atf3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO CONDUCT WIRING CHECKS.		80.00	30.00
	TRANSFER LH FRONT AND REAR DOOR.		200.00	80.00
	TO REMOVE AND REFIX FRONT UNDERCARRIAGE.		250.00	200.00
	WHEEL ALIGNMENT.		120.00	80.00
			3,350.00	2,090.00
GRAND TOTAL			15,947.91	6,776.85
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				5,400.00

Report Ref No. CS/AGI21011467/Atf3n2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.