

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/EQI21011469/EQF3N2**Date:** 10/12/2021REFERENCE

Handling Insurer:	EQ Insurance Company Ltd	Policy No:	DMPPHQ21-000830
Claimant Vehicle No :	GBG2767Y	Insured Vehicle No :	SMR7323Z
Date of Loss:	05/11/2021	Nature of Claim:	TP
		Claim No:	DM21HO01666

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBG2767Y		
Make & Model:	TOYOTA HIACE, 3.0 D TURBO 5 DR (M)	Engine No:	1KD2697120
Reg. Date:	07/07/2017 (Man. Year: 2017)	Chassis No:	JTFHT02P000219360
Colour:	Silver	Odometer:	147902 km
Engine Capacity:	2982 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195R15	Rear Tyre Size:	195R15
Front Left Side:	Bridgestone 5 mm	Rear Left Side:	Bridgestone 5 mm
Front Right Side:	Bridgestone 5 mm	Rear Right Side:	Bridgestone 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,360.70	5,398.37	962.33	15.13
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,580.00	1,990.00	590.00	22.87
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,940.70	7,388.37	1,552.33	17.36
Approved Total (Overridden) (S\$)		5,900.00		
(S\$)	8,940.70	5,900.00	3,040.70	34.01
+ GST 7.00/7.00% (S\$)	625.85	413.00	212.85	34.01
Nett Amount (S\$)	9,566.55	6,313.00	3,253.55	34.01

INSPECTION

Date of Assignment:	10/11/2021	
Date Inspected:	10/11/2021	Inspected At: 15 FAN YONG ROAD SINGAPORE 629792 REPAIRER: MOVA AUTOMOTIVE PTE LTD
Estimated Period of Repair:	11.0 days	

Adjuster: CHEN TSUE YEE**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 10 Dec 2021)
Parts:	213	TOYOTA HIACE 3.0 D TURBO 5 DR (M) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBG2767Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Dented	2,150.00 FL	*1,969.00 FL
2	1		*TAILGATE GLASS SEALANT	Necessary	40.00 FS	*40.00 FS
3	1		*TAILGATE LOGO	Necessary	65.00 FL	*65.00 FL
4	1		*TAILGATE STICKER - TOYOTA	Necessary	65.00 FL	*65.00 FL
5	1		*TAILGATE STICKER -70KM/H	Necessary	10.00 FS	*10.00 FS
6	1		*TAILGATE LOCK	Bent	275.00 FL	*275.00 FL
7	1		*TAILGATE WEATHERSTRIP	Torn	395.00 FL	*395.00 FL
8	1		*TAILGATE STOPPER - RH	Not Necessary	20.00 FL	*- FL
9	1		*TAILGATE INNER TRIM - CHECK (Npa)	Not Necessary	-	*- FL
10	1		*TAILGATE ASSY RH	Broken	360.00 FL	*360.00 FL
11	1		*TAILLAMP PANEL RH	Dented	283.40 FL	*283.40 FL
12	1		*TAILLAMP LOWER GARNISH RH	Missing	100.00 FL	*100.00 FL
13	1		*REAR BUMPER	Broken	415.00 FL	*415.00 FL
14	1		*REAR BUMPER BRACKET RH	Bent	31.00 FL	*31.00 FL
15	1		*REAR BUMPER RETAINER RH	Broken	31.00 FL	*31.00 FL
16	1		*TAILLAMP LOWER GARNISH RETAINER RH	Broken	30.00 FL	*30.00 FL
17	1		*REVERSE SENSOR	Broken	200.00 FS	*200.00 FS
18	1		*REAR FENDER RH	Dented	1,580.00 FL	*1,580.00 FL
19	1		*REAR FENDER INNER TRIM RH	Torn	555.10 FL	*555.10 FL
20	1		*REAR FENDER INNER PANEL RH (REPAIR) (Npa)	Repair	-	-
21	1		*REAR FENDER AIR DUCT RH	Broken	110.00 FL	*110.00 FL
22	1		*REAR SLIDING DOOR RAILING RH	Not Necessary	332.10 FL	*- FL
23	1		*REAR SLIDING DOOR RAILING END COVER RH	Not Necessary	90.00 FL	*- FL
24	1		*REAR EXHAUST SILENCER	Not Necessary	295.00 FL	*- FL
25	3		*REAR EXHAUST MOUNTING	Not Necessary	135.00 FL	*- FL
26	1		*TAILGATE GRAPHIC STICKER	Necessary	350.00 FL	*200.00 FS
27	1		*REAR FENDER GRAPHIC STICKER	Necessary	480.00 FL	*250.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	8,397.60	6,964.50
- List Item Discount on L Items 25.00/25.00% (\$)	2,036.90	1,566.13
Total Parts (\$)	6,360.70	5,398.37

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CUT/WELD REAR FEDNER RH, TAILLAMP PANEL RH, REAR END PANEL. REMOVE & REPLACE ACCIDENT DAMAGED PARTS. REALIGN ALL CONNECTION	New	1,000.00	900.00
2	SPRAY PAINT REAR FENDER RH, TAILLAMP PANEL RH, REAR END PANEL, TAILGATE, REAR BUMPER, REAR INNER PANEL RH, REAR FLOOR PANEL	New	1,000.00	800.00
3	REMOVE & REPLACE TAILGATE GLASS & CHECK WATER LEAKAGE	New	120.00	120.00
4	REMOVE & REPLACE TAILGATE INNER TRIM, MECHANISM & CHECK LOCKING SYSTEM	New	60.00	50.00
5	REMOVE & REPLACE REAR FENDER INNER TRIM, UPHOUSTERY,GARNISH	New	150.00	30.00
6	REMOVE & REPLACE REVERSE SENSOR & CHECK FUNCTION	New	50.00	30.00
7	RUST PROOF AFFECTED AREAS	New	100.00	30.00
8	TO APPPLY SEAL ON WELDING JOINT	New	100.00	30.00
Gross Labour Cost (\$\$)			2,580.00	1,990.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >