

**Note: This document has not been finalised.**

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: EQ Insurance Company Ltd  
5 Maxwell Road,#17-00 Tower  
Block  
MND Complex  
Singapore 069110

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Melody Teoh

Date: 09 Dec 2021

**Preliminary Advice**

Insured : SMR7323Z

Vehicle No

TP Vehicle : GBG2767Y  
No

Accident Date : 05/11/2021

Make : TOYOTA HIACE

Assignment Date : 10/11/2021

Date of : 10/11/2021

Est. Duration of : 11  
Repair

Inspection At : MOVA AUTOMOTIVE PTE LTD (BUKIT MERAH)  
BLK 1008, #01-04/06/08/94, BUKIT MERAH LANE 3  
SINGAPORE 159722

**Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	8,940.70
Revised Amount	:S\$	7,388.38
Check Items (Estimated)	:S\$	0.00
Total	:S\$	7,388.38

Lump Sum Repair	:S\$	5,900.00
-----------------	------	----------

**Total Loss Consideration**

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$

Salvage Value	:S\$
Margin for Repair	:S\$

**Remarks**

- ( ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( X ) Other comments : Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour cost.