

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS3/AIG21011471/R1VF3Q2
Date: 20/11/2021REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1700048650
Claimant Vehicle No :	SLU8798B	Insured Vehicle No :	SJJ7886T
Date of Loss:	09/11/2021	Nature of Claim:	TP
		Claim No:	5592447019SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLU8798B	Engine No:	G4FGHU830754
Make & Model:	HYUNDAI ELANTRA, 1.6 (A)	Chassis No:	KMHD841CMJU591853
Reg. Date:	18/12/2017 (Man. Year: 2017)	Odometer:	66834 km
Colour:	White		
Engine Capacity:	1591 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	215/45 R17	Rear Tyre Size:	215/45 R17
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

11/20/21, 2:10 PM

Adjuster Report

Date of Assignment: 10/11/2021

Date Inspected: 10/11/2021

Estimated Period of Repair: 7.0 days

Inspected At:

Teck Siang Motor Service (HQ)
Block 5034 Ang Mo Kio Industrial Park 2 #01-331
Singapore 569537

Adjuster: MOHD RASUL

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

MARKET VALUE: \$57,000.00

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT BUMPER	Cut	0.00 F	*- F
2	1		*FRT BUMPER CLIPS	Necessary	0.00 F	*- F
3	1		*FRT GRILLE	Cracked	0.00 F	*- F
4	1		*REAR NUMBER PLATE	Cracked	0.00 F	*- F
5	1		*REAR BUMPER	Deformed	0.00 F	*- F
6	1		*REAR BUMPER CLIPS	Necessary	0.00 F	*- F
7	2		*REAR BUMPER REFLECTOR	Scratched	0.00 F	*- F
8	1		*REAR BUMPER LOWER SPOILER	Cracked	0.00 F	*- F
9	1		*REAR LH TAILLAMP	Cracked	0.00 F	*- F
10	1		*REAR RH TAILLAMP	Cracked	0.00 F	*- F
11	1		*BOOTLID	Bent	0.00 F	*- F
12	1		*BOOTLID EMBLEM	Necessary	0.00 F	*- F
13	1		*BOOTLID LAMP RH	Cracked	0.00 F	*- F
14	1		*BOOTLID LOCK	Scratched	0.00 F	*- F
15	1		*BOOTLID RUBBER	Necessary	0.00 F	*- F
Total Parts (S\$)					0.00	0.00

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >