



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SCG 72U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BUMPER	DEFORMED	1,890.00	1,890.00
1	FRONT BUMPER SIDE HOLDER LH	NOT NECESSARY	112.40	-
1	FRONT BUMPER SPONGE	CRACKED	149.50	149.50
1	FRONT BUMPER REINFORCEMENT	NOT NECESSARY	745.90	-
1	FRONT BUMPER SIDE LAMP LH	CRACKED	380.40	380.40
1	FRONT BUMPER SENSOR	NOT NECESSARY	285.00	-
1	FRONT BUMPER NOZZLE PUMP	NOT NECESSARY	338.30	-
1	FRONT BUMPER LOGO	NECESSARY	85.00	85.00
1	HEADLAMP LH	CRACKED	4,510.00	4,510.00
	LESS 10% DISCOUNT		-	-701.49
			8,496.50	6,313.41
	<u>SPECIAL NETT ITEMS</u>			
1	FRONT BUMPER CLIPS (SN)	NECESSARY	50.00	50.00
			50.00	50.00
	<u>LABOUR</u>			
	PANEL BEATING.		600.00	300.00
	SPRAY PAINTING.		500.00	250.00
	WIRING.		50.00	30.00
	TO REMOVE REVERSE SENSOR.		100.00	50.00
	TO PERFORM DIAGNOSTIC TEST.		150.00	100.00
			1,400.00	730.00
	GRAND TOTAL		9,946.50	7,093.41
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			5,650.00

Report Ref No. CS/TP21011472/Atce2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.