

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile | | | | | | |
|---|--|---|----------------|-------|---------------------|--|
| | MIRAGE MOTORV | VERKZ PTE LTD | | Ref: | CS/TP21011472/Atce2 | |
| | 10 KAKI BUKIT RC #01-29 FIRST EAST CENT | ΓRE | | Date: | 29/11/2021 | |
| | SINGAPORE 4178 | | | | TRESS | |
| | ON BEHALF OF N | | | Code: | TP538 | |
| 1. | Policy Particulars :- THIRD PARTY CLAIM | | | | | |
| | Insured Veh. | | Veh. Inspected | l | SCG 72U | |
| | Policy No. | | Coverage (\$) | | 0.00 | |
| | Claim No. | | Excess (\$) | | 0.00 | |
| - | Assign From | | Assign Date | | 28/10/2021 | |
| 2. Vehicle Particulars & Condition | | | | | | |
| | Make & Model | B.M.W. 640I CONVERTIBLE | c.c | | 2979 | |
| | Engine No. | HIDDEN | Year of Reg. | | 2012 | |
| | Chassis No. | WBALW72070DK15592 | Colour | | BLACK | |
| | Odometer | 87359 KM | Steering | | IN ORDER | |
| | Brakes | IN ORDER | Modification | | SPORTS RIM | |
| _ | General | GOOD | | | | |
| 3. | | | | | | |
| | | Size | Make | | Balance | |
| | R/H Front Tyre | 245/35 R20 | LANDSAIL | | 6 mm | |
| | L/H Front Tyre | 245/35 R20 | LANDSAIL | | 6 mm | |
| | R/H Rear Tyre | 245/35 R20 | LANDSAIL | | 6 mm | |
| | L/H Rear Tyre | 245/35 R20 | LANDSAIL | | 6 mm | |
| 4. | Description of Damages | | | | | |
| | THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION. | | | | | |
| | DAMAGES SEE DETAILS. | | | | | |
| 5. | General Information | | | | | |
| | Accident Date | 08/10/2021 | Inspection Dat | е | 28/10/2021 | |
| | Survey held at | MIRAGE MOTORWERKZ PTE L | .TD | | | |
| | | 10 KAKI BUKIT ROAD 2 #01-29 FIRST EAST CENTRE SINGAPORE 417868 | | | | |
| 5a. | 5a. Remarks | | | | | |
| | A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. | | | | | |
| 5b. | Estimate Days of Repair | | | | | |
| | ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days | | | | | |